

IGNITION INTERLOCK DEVICES INSTALLED AT END OF MONTH

| | AUG 2010 | SEP 2010 | OCT 2010 | NOV 2010 | DEC 2010 | JAN 2011 | FEB 2011 | MAR 2011 | APR 2011 | MAY 2011 | JUN 2011 | JUL 2011 | AUG 2011 | SEP 2011 | OCT 2011 | NOV 2011 | DEC 2011 | JAN 2012 | FEB 2012 | MAR 2012 | APR 2012 | MAY 2012 |
|--|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|
| 1A Lifesafers, Inc. | 533 | 560 | 592 | 642 | 699 | 762 | 843 | 789 | 860 | 1066 | 1146 | 1197 | 1228 | 1264 | 1274 | 1321 | 1241 | 1545 | 1585 | 1638 | 1654 | 1665 |
| LifeSafer FC100 camera | 16 | 19 | 45 | 81 | 137 | 183 | 256 | 265 | 341 | 485 | 581 | 619 | 666 | 699 | 731 | 767 | 755 | 1066 | 1087 | 1154 | 1169 | 1181 |
| LifeSafer FC100 no camera | 517 | 541 | 547 | 561 | 562 | 579 | 587 | 524 | 519 | 581 | 565 | 578 | 562 | 565 | 543 | 554 | 486 | 479 | 498 | 484 | 485 | 484 |
| 1A Smart Start, Inc. | 420 | 492 | 648 | 809 | 980 | 1137 | 1335 | 1538 | 1635 | 1749 | 1817 | 1872 | 1879 | 1848 | 1821 | 1808 | 1760 | 1747 | 1736 | 1729 | 1682 | 1680 |
| Smart Start 2020 | 160 | 245 | 407 | 587 | 773 | 943 | 1157 | 1374 | 1485 | 1605 | 1693 | 1756 | 1775 | 1756 | 1738 | 1738 | 1706 | 1702 | 1699 | 1696 | 1655 | 1656 |
| Smart Start SS1-1000 | 260 | 247 | 241 | 222 | 207 | 194 | 178 | 164 | 150 | 144 | 124 | 116 | 104 | 92 | 83 | 70 | 54 | 45 | 37 | 33 | 27 | 24 |
| Consumer Safety Technology, Inc. | 0 | 41 | 106 | 202 | 327 | 432 | 524 | 585 | 698 | 806 | 902 | 1079 | 1133 | 1193 | 1234 | 1365 | 1378 | 1428 | 1507 | 1611 | 1665 | 1713 |
| Intoxalock 1001A | 0 | 16 | 37 | 80 | 120 | 153 | 183 | 201 | 244 | 276 | 293 | 334 | 346 | 344 | 339 | 327 | 307 | 306 | 318 | 317 | 332 | 330 |
| Intoxalock 1001A Advanced | 0 | 25 | 69 | 122 | 207 | 279 | 341 | 384 | 454 | 530 | 609 | 745 | 787 | 849 | 895 | 1038 | 1071 | 1122 | 1189 | 1294 | 1333 | 1383 |
| Draeger Safety Diagnostics, Inc. | 658 | 676 | 705 | 723 | 754 | 785 | 823 | 852 | 851 | 866 | 818 | 799 | 776 | 782 | 758 | 744 | 732 | 759 | 731 | 736 | 727 | 620 |
| Draeger XT | 658 | 676 | 705 | 723 | 754 | 785 | 823 | 852 | 851 | 866 | 818 | 799 | 776 | 782 | 758 | 744 | 732 | 759 | 731 | 736 | 727 | 620 |
| Interceptor Ignition Interlocks, Inc. | 521 | 558 | 611 | 687 | 764 | 811 | 883 | 973 | 1064 | 1100 | 1183 | 1245 | 1300 | 1357 | 1408 | 1444 | 1474 | 1509 | 1543 | 1557 | 1572 | 1257 |
| Interceptor M-1 | 521 | 558 | 611 | 687 | 764 | 811 | 883 | 973 | 1064 | 1100 | 1183 | 1245 | 1300 | 1357 | 1408 | 1444 | 1474 | 1509 | 1543 | 1557 | 1572 | 1257 |
| Sens_O-Lock of America, L.L.C. | | 47 | 61 | 74 | 88 | 90 | 106 | 106 | 119 | 121 | 121 | 114 | 108 | 110 | 98 | 86 | 82 | 65 | 58 | 52 | 58 | 66 |
| Best Labs FR9000 | | 47 | 61 | 74 | 88 | 90 | 106 | 106 | 119 | 121 | 121 | 114 | 108 | 110 | 98 | 86 | 82 | 65 | 58 | 52 | 58 | 66 |
| Statewide Interlock Systemes, Inc. | | | | | | | | | | | | 0 | 4 | 7 | 8 | 9 | 13 | 13 | 14 | 9 | 9 | 11 |
| Alcohol Detection Systems DM-904 | | | | | | | | | | | | 0 | 4 | 7 | 8 | 9 | 13 | 13 | 14 | 9 | 9 | 11 |
| Grand Total | 2132 | 2374 | 2723 | 3137 | 3612 | 4017 | 4514 | 4843 | 5227 | 5708 | 5987 | 6306 | 6428 | 6561 | 6601 | 6777 | 6680 | 7066 | 7174 | 7332 | 7367 | 7012 |