

IGNITION INTERLOCK DEVICES INSTALLED AT END OF MONTH

|  | Aug-10    | Sep-10     | Oct-10     | Nov-10     | Dec-10     | Jan-11     | Feb-11     | Mar-11     | Apr-11     | May-11     | Jun-11     | Jul-11     | Aug-11     | Sep-11     | 11-Oct     | 11-Nov     | Dec-11     |
|--|-----------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|
| <b>Albany</b>                                | <b>92</b> | <b>109</b> | <b>122</b> | <b>135</b> | <b>156</b> | <b>180</b> | <b>199</b> | <b>201</b> | <b>229</b> | <b>230</b> | <b>238</b> | <b>232</b> | <b>238</b> | <b>244</b> | <b>249</b> | <b>247</b> | <b>254</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>2</b>  | <b>8</b>   | <b>12</b>  | <b>13</b>  | <b>17</b>  | <b>24</b>  | <b>30</b>  | <b>34</b>  | <b>39</b>  | <b>46</b>  | <b>46</b>  | <b>45</b>  | <b>50</b>  | <b>49</b>  | <b>54</b>  | <b>54</b>  | <b>61</b>  |
| Smart Start 2020                             | 1         | 6          | 10         | 11         | 15         | 22         | 29         | 33         | 38         | 45         | 45         | 44         | 49         | 48         | 53         | 53         | 60         |
| Smart Start SS1-1000                         | 1         | 2          | 2          | 2          | 2          | 2          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>0</b>   | <b>1</b>   | <b>2</b>   | <b>3</b>   | <b>5</b>   | <b>5</b>   | <b>5</b>   | <b>8</b>   | <b>8</b>   | <b>12</b>  | <b>11</b>  | <b>14</b>  | <b>17</b>  | <b>25</b>  | <b>29</b>  | <b>34</b>  |
| Intoxalock 1001A                             | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| Intoxalock 1001A Advanced                    | 0         | 0          | 1          | 2          | 3          | 5          | 5          | 5          | 8          | 8          | 12         | 11         | 14         | 17         | 25         | 29         | 34         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>7</b>  | <b>7</b>   | <b>7</b>   | <b>6</b>   | <b>7</b>   | <b>7</b>   | <b>8</b>   | <b>8</b>   | <b>8</b>   | <b>7</b>   | <b>7</b>   | <b>7</b>   | <b>5</b>   | <b>5</b>   | <b>5</b>   | <b>5</b>   | <b>5</b>   |
| Draeger XT                                   | 7         | 7          | 7          | 6          | 7          | 7          | 8          | 8          | 8          | 7          | 7          | 7          | 5          | 5          | 5          | 5          | 5          |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>79</b> | <b>83</b>  | <b>86</b>  | <b>90</b>  | <b>95</b>  | <b>100</b> | <b>104</b> | <b>105</b> | <b>105</b> | <b>102</b> | <b>102</b> | <b>102</b> | <b>102</b> | <b>103</b> | <b>100</b> | <b>93</b>  | <b>90</b>  |
| Interceptor M-1                              | 79        | 83         | 86         | 90         | 95         | 100        | 104        | 105        | 105        | 102        | 102        | 102        | 102        | 103        | 100        | 93         | 90         |
| <b>National Interlock Service LTD</b>        | <b>4</b>  | <b>9</b>   | <b>14</b>  | <b>21</b>  | <b>30</b>  | <b>40</b>  | <b>48</b>  | <b>46</b>  | <b>67</b>  | <b>66</b>  | <b>70</b>  | <b>66</b>  | <b>66</b>  | <b>69</b>  | <b>64</b>  | <b>65</b>  | <b>63</b>  |
| LifeSafer FC100 camera                       | 0         | 0          | 6          | 13         | 22         | 30         | 38         | 39         | 65         | 64         | 68         | 64         | 65         | 68         | 62         | 63         | 61         |
| LifeSafer FC100 no camera                    | 4         | 9          | 8          | 8          | 8          | 10         | 10         | 7          | 2          | 2          | 2          | 2          | 1          | 1          | 2          | 2          | 2          |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>2</b>   | <b>2</b>   | <b>3</b>   | <b>4</b>   | <b>4</b>   | <b>4</b>   | <b>3</b>   | <b>2</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   |
| Best Labs FR9000                             |           | 2          | 2          | 3          | 4          | 4          | 4          | 3          | 2          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |            |            |            |            |            |            |            |            |            |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Alcohol Detection Systems DM-904             |           |            |            |            |            |            |            |            |            |            |            | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Allegany</b>                              | <b>0</b>  | <b>0</b>   | <b>1</b>   | <b>3</b>   | <b>3</b>   | <b>5</b>   | <b>6</b>   | <b>8</b>   | <b>11</b>  | <b>11</b>  | <b>10</b>  | <b>10</b>  | <b>11</b>  | <b>13</b>  | <b>12</b>  | <b>13</b>  | <b>12</b>  |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>  | <b>0</b>   | <b>0</b>   | <b>2</b>   | <b>2</b>   | <b>3</b>   | <b>3</b>   | <b>4</b>   | <b>4</b>   | <b>4</b>   | <b>3</b>   | <b>2</b>   | <b>2</b>   | <b>3</b>   | <b>3</b>   | <b>3</b>   | <b>3</b>   |
| Smart Start 2020                             | 0         | 0          | 0          | 2          | 2          | 3          | 3          | 4          | 4          | 4          | 3          | 2          | 2          | 3          | 3          | 3          | 3          |
| Smart Start SS1-1000                         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>2</b>   | <b>3</b>   | <b>4</b>   | <b>6</b>   | <b>6</b>   | <b>6</b>   | <b>6</b>   | <b>7</b>   | <b>8</b>   | <b>7</b>   | <b>8</b>   | <b>8</b>   |
| Intoxalock 1001A                             | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| Intoxalock 1001A Advanced                    | 0         | 0          | 1          | 1          | 1          | 2          | 3          | 4          | 6          | 6          | 6          | 6          | 7          | 8          | 7          | 8          | 8          |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b>  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Draeger XT                                   | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b>  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Interceptor M-1                              | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>National Interlock Service LTD</b>        | <b>0</b>  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>1</b>   |
| LifeSafer FC100 camera                       | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 0          |
| LifeSafer FC100 no camera                    | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 1          | 1          | 1          | 1          | 1          | 1          |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Best Labs FR9000                             |           | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |            |            |            |            |            |            |            |            |            |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Alcohol Detection Systems DM-904             |           |            |            |            |            |            |            |            |            |            |            | 0          | 0          | 0          | 0          | 0          | 0          |

|  |           |           |           |           |           |           |           |           |           |           |           |            |           |           |           |           |           |
|--|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|------------|-----------|-----------|-----------|-----------|-----------|
| <b>Bronx</b>                                 | <b>1</b>  | <b>1</b>  | <b>8</b>  | <b>12</b> | <b>21</b> | <b>23</b> | <b>29</b> | <b>38</b> | <b>46</b> | <b>52</b> | <b>50</b> | <b>55</b>  | <b>51</b> | <b>46</b> | <b>59</b> | <b>60</b> | <b>66</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>  | <b>0</b>  | <b>4</b>  | <b>8</b>  | <b>11</b> | <b>12</b> | <b>16</b> | <b>24</b> | <b>27</b> | <b>32</b> | <b>27</b> | <b>31</b>  | <b>29</b> | <b>29</b> | <b>32</b> | <b>32</b> | <b>32</b> |
| Smart Start 2020                             | 0         | 0         | 4         | 8         | 11        | 12        | 16        | 24        | 27        | 32        | 27        | 31         | 29        | 29        | 32        | 32        | 32        |
| Smart Start SS1-1000                         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>4</b>  | <b>5</b>  | <b>5</b>  | <b>6</b>  | <b>6</b>  | <b>7</b>  | <b>11</b> | <b>7</b>   | <b>7</b>  | <b>7</b>  | <b>10</b> | <b>11</b> | <b>11</b> |
| Intoxalock 1001A                             | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0         | 0         | 0         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0         | 0         | 1         | 1         | 4         | 5         | 5         | 6         | 6         | 7         | 11        | 7          | 7         | 7         | 10        | 11        | 11        |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>   | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>   | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  |
| Interceptor M-1                              | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1          | 1         | 1         | 2         | 2         | 2         |
| <b>National Interlock Service LTD</b>        | <b>0</b>  | <b>0</b>  | <b>2</b>  | <b>2</b>  | <b>5</b>  | <b>5</b>  | <b>7</b>  | <b>7</b>  | <b>12</b> | <b>12</b> | <b>11</b> | <b>16</b>  | <b>14</b> | <b>9</b>  | <b>15</b> | <b>14</b> | <b>20</b> |
| LifeSafer FC100 camera                       | 0         | 0         | 1         | 1         | 4         | 4         | 6         | 6         | 11        | 11        | 11        | 14         | 12        | 8         | 14        | 13        | 19        |
| LifeSafer FC100 no camera                    | 0         | 0         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 0         | 2          | 2         | 1         | 1         | 1         | 1         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>   | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  |
| Best Labs FR9000                             |           | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0         | 0         | 0         | 1         | 1         |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |           |           |           |           |           |           |           |           |           |           | <b>0</b>   | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |           |           |           |           |           |           |           |           |           |           |           | 0          | 0         | 0         | 0         | 0         | 0         |
| <b>Broome</b>                                | <b>21</b> | <b>27</b> | <b>32</b> | <b>39</b> | <b>47</b> | <b>55</b> | <b>67</b> | <b>64</b> | <b>80</b> | <b>80</b> | <b>82</b> | <b>101</b> | <b>98</b> | <b>95</b> | <b>89</b> | <b>94</b> | <b>87</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>  | <b>4</b>  | <b>6</b>  | <b>8</b>  | <b>12</b> | <b>14</b> | <b>16</b> | <b>14</b> | <b>14</b> | <b>12</b> | <b>9</b>  | <b>7</b>   | <b>4</b>  | <b>5</b>  | <b>2</b>  | <b>2</b>  | <b>1</b>  |
| Smart Start 2020                             | 0         | 4         | 6         | 8         | 12        | 14        | 16        | 14        | 14        | 12        | 9         | 7          | 4         | 5         | 2         | 2         | 1         |
| Smart Start SS1-1000                         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>2</b>  | <b>3</b>  | <b>4</b>  | <b>4</b>  | <b>5</b>  | <b>8</b>  | <b>8</b>  | <b>11</b> | <b>10</b> | <b>15</b> | <b>26</b>  | <b>27</b> | <b>28</b> | <b>32</b> | <b>35</b> | <b>27</b> |
| Intoxalock 1001A                             | 0         | 2         | 3         | 4         | 4         | 5         | 7         | 7         | 8         | 7         | 12        | 23         | 24        | 25        | 28        | 30        | 22        |
| Intoxalock 1001A Advanced                    | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 3         | 3         | 3         | 3          | 3         | 3         | 4         | 5         | 5         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>2</b>  | <b>3</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>   | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  |
| Draeger XT                                   | 3         | 3         | 3         | 3         | 3         | 3         | 3         | 2         | 3         | 4         | 4         | 4          | 4         | 4         | 4         | 4         | 4         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>9</b>  | <b>9</b>  | <b>10</b> | <b>10</b> | <b>10</b> | <b>10</b> | <b>11</b> | <b>11</b> | <b>13</b> | <b>13</b> | <b>13</b> | <b>13</b>  | <b>13</b> | <b>14</b> | <b>15</b> | <b>15</b> | <b>15</b> |
| Interceptor M-1                              | 9         | 9         | 10        | 10        | 10        | 10        | 11        | 11        | 13        | 13        | 13        | 13         | 13        | 14        | 15        | 15        | 15        |
| <b>National Interlock Service LTD</b>        | <b>9</b>  | <b>8</b>  | <b>9</b>  | <b>13</b> | <b>13</b> | <b>18</b> | <b>18</b> | <b>16</b> | <b>24</b> | <b>26</b> | <b>26</b> | <b>35</b>  | <b>37</b> | <b>30</b> | <b>25</b> | <b>28</b> | <b>28</b> |
| LifeSafer FC100 camera                       | 0         | 0         | 0         | 1         | 1         | 4         | 3         | 3         | 2         | 2         | 0         | 2          | 3         | 3         | 3         | 3         | 4         |
| LifeSafer FC100 no camera                    | 9         | 8         | 9         | 12        | 12        | 14        | 15        | 13        | 22        | 24        | 26        | 33         | 34        | 27        | 22        | 25        | 24        |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>5</b>  | <b>5</b>  | <b>11</b> | <b>13</b> | <b>15</b> | <b>15</b> | <b>15</b> | <b>16</b>  | <b>13</b> | <b>14</b> | <b>11</b> | <b>10</b> | <b>12</b> |
| Best Labs FR9000                             |           | 1         | 1         | 1         | 5         | 5         | 11        | 13        | 15        | 15        | 15        | 16         | 13        | 14        | 11        | 10        | 12        |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |           |           |           |           |           |           |           |           |           |           | <b>0</b>   | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |           |           |           |           |           |           |           |           |           |           |           | 0          | 0         | 0         | 0         | 0         | 0         |

|  |          |          |           |           |           |           |           |           |           |           |           |           |           |           |           |           |           |
|--|----------|----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| <b>Cattaraugus</b>                           | <b>0</b> | <b>4</b> | <b>10</b> | <b>14</b> | <b>25</b> | <b>28</b> | <b>29</b> | <b>31</b> | <b>31</b> | <b>36</b> | <b>35</b> | <b>28</b> | <b>35</b> | <b>38</b> | <b>42</b> | <b>43</b> | <b>39</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>3</b> | <b>8</b>  | <b>9</b>  | <b>16</b> | <b>20</b> | <b>21</b> | <b>24</b> | <b>22</b> | <b>25</b> | <b>24</b> | <b>18</b> | <b>21</b> | <b>23</b> | <b>23</b> | <b>23</b> | <b>18</b> |
| Smart Start 2020                             | 0        | 3        | 8         | 9         | 16        | 20        | 21        | 24        | 22        | 25        | 24        | 18        | 21        | 23        | 23        | 23        | 18        |
| Smart Start SS1-1000                         | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>0</b> | <b>1</b>  | <b>2</b>  | <b>6</b>  | <b>6</b>  | <b>6</b>  | <b>5</b>  | <b>5</b>  | <b>5</b>  | <b>5</b>  | <b>4</b>  | <b>5</b>  | <b>5</b>  | <b>6</b>  | <b>9</b>  | <b>13</b> |
| Intoxalock 1001A                             | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0        | 0        | 1         | 2         | 6         | 6         | 6         | 5         | 5         | 5         | 5         | 4         | 5         | 5         | 6         | 9         | 13        |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>2</b>  | <b>2</b>  | <b>3</b>  | <b>6</b>  | <b>7</b>  | <b>10</b> | <b>8</b>  | <b>6</b>  |
| Draeger XT                                   | 0        | 0        | 0         | 1         | 1         | 0         | 0         | 0         | 0         | 2         | 2         | 3         | 6         | 7         | 10        | 8         | 6         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Interceptor M-1                              | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>1</b> | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>2</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         |
| LifeSafer FC100 no camera                    | 0        | 1        | 1         | 2         | 2         | 2         | 2         | 2         | 3         | 3         | 3         | 2         | 2         | 2         | 2         | 2         | 1         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |           |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |           |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Cayuga</b>                                | <b>1</b> | <b>3</b> | <b>8</b>  | <b>10</b> | <b>13</b> | <b>16</b> | <b>16</b> | <b>19</b> | <b>26</b> | <b>25</b> | <b>27</b> | <b>27</b> | <b>24</b> | <b>27</b> | <b>28</b> | <b>28</b> | <b>25</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>1</b> | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>5</b>  | <b>5</b>  | <b>7</b>  | <b>8</b>  | <b>7</b>  | <b>7</b>  | <b>7</b>  | <b>6</b>  | <b>6</b>  | <b>6</b>  | <b>6</b>  | <b>3</b>  |
| Smart Start 2020                             | 0        | 1        | 2         | 3         | 3         | 5         | 5         | 7         | 8         | 7         | 7         | 7         | 6         | 6         | 6         | 6         | 3         |
| Smart Start SS1-1000                         | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>1</b> | <b>4</b>  | <b>5</b>  | <b>7</b>  | <b>8</b>  | <b>8</b>  | <b>10</b> | <b>12</b> | <b>13</b> | <b>15</b> | <b>15</b> | <b>15</b> | <b>17</b> | <b>18</b> | <b>18</b> | <b>19</b> |
| Intoxalock 1001A                             | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 0         | 0         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0        | 1        | 4         | 5         | 7         | 8         | 8         | 10        | 12        | 13        | 15        | 14        | 14        | 17        | 18        | 18        | 19        |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Interceptor M-1                              | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>National Interlock Service LTD</b>        | <b>1</b> | <b>1</b> | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>5</b>  | <b>5</b>  | <b>5</b>  | <b>5</b>  | <b>3</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>3</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 4         | 4         | 4         | 4         | 2         | 3         | 3         | 3         | 3         |
| LifeSafer FC100 no camera                    | 1        | 1        | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 0         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b> | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0        | 1         | 1         | 2         | 2         | 2         | 1         | 1         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |           |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |           |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |

|  |          |           |           |           |           |           |           |           |           |           |           |           |           |           |           |           |           |
|--|----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| <b>Chautauqua</b>                            | <b>0</b> | <b>0</b>  | <b>2</b>  | <b>4</b>  | <b>6</b>  | <b>10</b> | <b>16</b> | <b>19</b> | <b>24</b> | <b>27</b> | <b>31</b> | <b>30</b> | <b>31</b> | <b>37</b> | <b>36</b> | <b>35</b> | <b>31</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>4</b>  | <b>7</b>  | <b>8</b>  | <b>10</b> | <b>8</b>  | <b>10</b> | <b>7</b>  | <b>5</b>  | <b>5</b>  | <b>3</b>  | <b>3</b>  | <b>4</b>  |
| Smart Start 2020                             | 0        | 0         | 1         | 1         | 2         | 4         | 7         | 8         | 10        | 8         | 10        | 7         | 5         | 5         | 3         | 3         | 4         |
| Smart Start SS1-1000                         | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>2</b>  | <b>4</b>  | <b>6</b>  | <b>7</b>  | <b>9</b>  | <b>13</b> | <b>15</b> | <b>16</b> | <b>17</b> | <b>18</b> | <b>18</b> | <b>17</b> | <b>16</b> |
| Intoxalock 1001A                             | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0        | 0         | 0         | 1         | 2         | 4         | 6         | 7         | 9         | 13        | 15        | 16        | 17        | 18        | 18        | 17        | 16        |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Interceptor M-1                              | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>0</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>3</b>  | <b>4</b>  | <b>5</b>  | <b>6</b>  | <b>6</b>  | <b>7</b>  | <b>9</b>  | <b>14</b> | <b>15</b> | <b>15</b> | <b>11</b> |
| LifeSafer FC100 camera                       | 0        | 0         | 0         | 1         | 1         | 1         | 2         | 3         | 4         | 4         | 4         | 6         | 8         | 11        | 12        | 12        | 9         |
| LifeSafer FC100 no camera                    | 0        | 0         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 2         | 2         | 1         | 1         | 3         | 3         | 3         | 2         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |           |           |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |           |           |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Chemung</b>                               | <b>6</b> | <b>11</b> | <b>15</b> | <b>23</b> | <b>31</b> | <b>39</b> | <b>40</b> | <b>41</b> | <b>47</b> | <b>55</b> | <b>62</b> | <b>64</b> | <b>65</b> | <b>68</b> | <b>69</b> | <b>73</b> | <b>71</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>2</b>  | <b>3</b>  | <b>7</b>  | <b>13</b> | <b>21</b> | <b>22</b> | <b>24</b> | <b>29</b> | <b>30</b> | <b>33</b> | <b>31</b> | <b>31</b> | <b>30</b> | <b>29</b> | <b>29</b> | <b>26</b> |
| Smart Start 2020                             | 0        | 2         | 3         | 7         | 13        | 21        | 22        | 24        | 29        | 30        | 33        | 31        | 31        | 30        | 29        | 29        | 26        |
| Smart Start SS1-1000                         | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>3</b>  | <b>6</b>  | <b>10</b> | <b>11</b> | <b>11</b> | <b>11</b> | <b>11</b> | <b>12</b> | <b>18</b> | <b>22</b> | <b>27</b> | <b>29</b> | <b>33</b> | <b>34</b> | <b>37</b> | <b>39</b> |
| Intoxalock 1001A                             | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0        | 3         | 6         | 10        | 11        | 11        | 11        | 11        | 12        | 18        | 22        | 27        | 29        | 33        | 34        | 37        | 39        |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>3</b> | <b>3</b>  | <b>3</b>  | <b>4</b>  | <b>5</b>  | <b>5</b>  | <b>5</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>5</b>  | <b>5</b>  |
| Interceptor M-1                              | 3        | 3         | 3         | 4         | 5         | 5         | 5         | 4         | 4         | 4         | 4         | 4         | 4         | 4         | 4         | 5         | 5         |
| <b>National Interlock Service LTD</b>        | <b>3</b> | <b>3</b>  | <b>3</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>2</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>1</b>  |
| LifeSafer FC100 camera                       | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         |
| LifeSafer FC100 no camera                    | 3        | 3         | 3         | 2         | 2         | 2         | 2         | 2         | 1         | 2         | 2         | 1         | 0         | 0         | 1         | 1         | 0         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |           |           |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |           |           |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |

|  |           |           |           |           |           |           |           |           |           |           |           |           |           |           |           |           |           |
|--|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| <b>Chenango</b>                              | <b>7</b>  | <b>10</b> | <b>11</b> | <b>13</b> | <b>15</b> | <b>17</b> | <b>20</b> | <b>24</b> | <b>27</b> | <b>29</b> | <b>32</b> | <b>32</b> | <b>32</b> | <b>33</b> | <b>32</b> | <b>29</b> | <b>30</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>3</b>  | <b>4</b>  | <b>5</b>  | <b>4</b>  | <b>4</b>  | <b>5</b>  | <b>5</b>  | <b>6</b>  |
| Smart Start 2020                             | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 2         | 3         | 4         | 5         | 4         | 4         | 5         | 5         | 6         |
| Smart Start SS1-1000                         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>3</b>  | <b>6</b>  | <b>8</b>  | <b>6</b>  | <b>6</b>  | <b>8</b>  | <b>9</b>  | <b>8</b>  | <b>8</b>  |
| Intoxalock 1001A                             | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 2         | 3         | 2         | 2         | 4         | 5         | 3         | 3         |
| Intoxalock 1001A Advanced                    | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 2         | 4         | 5         | 4         | 4         | 4         | 4         | 5         | 5         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  |
| Draeger XT                                   | 0         | 0         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>7</b>  | <b>9</b>  | <b>9</b>  | <b>11</b> | <b>11</b> | <b>11</b> | <b>12</b> | <b>16</b> | <b>16</b> | <b>15</b> | <b>15</b> | <b>15</b> | <b>16</b> | <b>16</b> | <b>14</b> | <b>12</b> | <b>12</b> |
| Interceptor M-1                              | 7         | 9         | 9         | 11        | 11        | 11        | 12        | 16        | 16        | 15        | 15        | 15        | 16        | 16        | 14        | 12        | 12        |
| <b>National Interlock Service LTD</b>        | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  |
| LifeSafer FC100 camera                       | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 2         | 2         | 2         |
| LifeSafer FC100 no camera                    | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 0         | 0         | 1         | 1         | 0         | 0         | 0         | 0         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>3</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  |
| Best Labs FR9000                             |           | 1         | 1         | 1         | 2         | 2         | 3         | 3         | 4         | 4         | 4         | 4         | 4         | 3         | 1         | 1         | 1         |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |           |           |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |           |           |           |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Clinton</b>                               | <b>12</b> | <b>14</b> | <b>16</b> | <b>16</b> | <b>19</b> | <b>22</b> | <b>30</b> | <b>30</b> | <b>34</b> | <b>42</b> | <b>54</b> | <b>55</b> | <b>59</b> | <b>68</b> | <b>65</b> | <b>65</b> | <b>64</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>1</b>  | <b>5</b>  | <b>7</b>  | <b>10</b> | <b>11</b> | <b>13</b> | <b>18</b> | <b>16</b> | <b>16</b> | <b>19</b> |
| Smart Start 2020                             | 0         | 1         | 1         | 1         | 1         | 2         | 2         | 1         | 5         | 7         | 10        | 11        | 13        | 18        | 16        | 16        | 19        |
| Smart Start SS1-1000                         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>3</b>  | <b>8</b>  | <b>8</b>  | <b>9</b>  | <b>11</b> | <b>14</b> | <b>16</b> | <b>17</b> | <b>18</b> | <b>17</b> | <b>17</b> | <b>14</b> |
| Intoxalock 1001A                             | 0         | 0         | 0         | 0         | 0         | 1         | 5         | 5         | 7         | 7         | 9         | 11        | 11        | 11        | 10        | 10        | 8         |
| Intoxalock 1001A Advanced                    | 0         | 0         | 1         | 1         | 2         | 2         | 3         | 3         | 2         | 4         | 5         | 5         | 6         | 7         | 7         | 7         | 6         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  |
| Draeger XT                                   | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 1         | 1         | 2         | 2         | 2         | 2         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>12</b> | <b>13</b> | <b>14</b> | <b>14</b> | <b>15</b> | <b>15</b> | <b>17</b> | <b>17</b> | <b>17</b> | <b>17</b> | <b>20</b> | <b>20</b> | <b>20</b> | <b>20</b> | <b>20</b> | <b>21</b> | <b>21</b> |
| Interceptor M-1                              | 12        | 13        | 14        | 14        | 15        | 15        | 17        | 17        | 17        | 17        | 20        | 20        | 20        | 20        | 20        | 21        | 21        |
| <b>National Interlock Service LTD</b>        | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>2</b>  | <b>6</b>  | <b>9</b>  | <b>7</b>  | <b>8</b>  | <b>10</b> | <b>10</b> | <b>9</b>  | <b>7</b>  |
| LifeSafer FC100 camera                       | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 0         | 0         | 1         | 1         | 1         | 2         | 3         | 2         | 1         |
| LifeSafer FC100 no camera                    | 0         | 0         | 0         | 0         | 1         | 1         | 2         | 2         | 2         | 6         | 8         | 6         | 7         | 8         | 7         | 7         | 6         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |           | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |           |           |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  |
| Alcohol Detection Systems DM-904             |           |           |           |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 1         |

|  |          |          |          |          |           |           |           |           |           |           |           |           |           |           |           |           |           |
|--|----------|----------|----------|----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| <b>Columbia</b>                              | <b>0</b> | <b>3</b> | <b>4</b> | <b>5</b> | <b>9</b>  | <b>11</b> | <b>15</b> | <b>14</b> | <b>15</b> | <b>20</b> | <b>20</b> | <b>15</b> | <b>14</b> | <b>11</b> | <b>11</b> | <b>12</b> | <b>13</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>0</b> | <b>0</b> | <b>1</b> | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>2</b>  | <b>2</b>  | <b>1</b>  | <b>1</b>  | <b>3</b>  |
| Smart Start 2020                             | 0        | 0        | 0        | 1        | 1         | 1         | 2         | 3         | 3         | 2         | 3         | 3         | 2         | 2         | 1         | 1         | 3         |
| Smart Start SS1-1000                         | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>2</b> | <b>2</b> | <b>2</b> | <b>6</b>  | <b>7</b>  | <b>7</b>  | <b>7</b>  | <b>7</b>  | <b>6</b>  | <b>5</b>  | <b>2</b>  | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>4</b>  | <b>4</b>  |
| Intoxalock 1001A                             | 0        | 2        | 2        | 2        | 4         | 5         | 5         | 5         | 5         | 4         | 3         | 0         | 0         | 1         | 1         | 3         | 3         |
| Intoxalock 1001A Advanced                    | 0        | 0        | 0        | 0        | 2         | 2         | 2         | 2         | 2         | 2         | 2         | 2         | 2         | 2         | 2         | 1         | 1         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Interceptor M-1                              | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>1</b> | <b>2</b> | <b>2</b> | <b>2</b>  | <b>3</b>  | <b>6</b>  | <b>4</b>  | <b>4</b>  | <b>11</b> | <b>11</b> | <b>9</b>  | <b>9</b>  | <b>5</b>  | <b>6</b>  | <b>6</b>  | <b>6</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0        | 0        | 0         | 1         | 1         | 1         | 1         | 4         | 4         | 3         | 3         | 3         | 3         | 3         | 3         |
| LifeSafer FC100 no camera                    | 0        | 1        | 2        | 2        | 2         | 2         | 5         | 3         | 3         | 7         | 7         | 6         | 6         | 2         | 3         | 3         | 3         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |          |          |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |          |          |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Cortland</b>                              | <b>4</b> | <b>4</b> | <b>6</b> | <b>9</b> | <b>15</b> | <b>17</b> | <b>20</b> | <b>23</b> | <b>22</b> | <b>24</b> | <b>26</b> | <b>26</b> | <b>27</b> | <b>27</b> | <b>29</b> | <b>27</b> | <b>25</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>0</b> | <b>2</b> | <b>5</b> | <b>9</b>  | <b>9</b>  | <b>13</b> | <b>16</b> | <b>15</b> | <b>16</b> | <b>18</b> | <b>18</b> | <b>18</b> | <b>19</b> | <b>20</b> | <b>20</b> | <b>18</b> |
| Smart Start 2020                             | 0        | 0        | 2        | 5        | 9         | 9         | 13        | 16        | 15        | 16        | 18        | 18        | 18        | 19        | 20        | 20        | 18        |
| Smart Start SS1-1000                         | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>1</b> | <b>2</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>3</b>  | <b>3</b>  | <b>4</b>  | <b>4</b>  | <b>5</b>  | <b>3</b>  | <b>3</b>  |
| Intoxalock 1001A                             | 0        | 0        | 0        | 1        | 2         | 3         | 3         | 3         | 3         | 3         | 2         | 2         | 3         | 3         | 4         | 2         | 2         |
| Intoxalock 1001A Advanced                    | 0        | 0        | 0        | 0        | 0         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>2</b> | <b>2</b> | <b>2</b> | <b>2</b> | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  |
| Draeger XT                                   | 2        | 2        | 2        | 2        | 2         | 2         | 2         | 2         | 2         | 2         | 2         | 2         | 2         | 2         | 2         | 2         | 2         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Interceptor M-1                              | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>National Interlock Service LTD</b>        | <b>2</b> | <b>2</b> | <b>2</b> | <b>1</b> | <b>2</b>  | <b>2</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| LifeSafer FC100 no camera                    | 2        | 2        | 2        | 1        | 2         | 2         | 1         | 1         | 1         | 2         | 3         | 3         | 3         | 2         | 2         | 2         | 2         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |          |          |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |          |          |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         | 0         |

|  |           |           |           |           |           |           |            |            |            |            |            |            |            |            |            |            |            |
|--|-----------|-----------|-----------|-----------|-----------|-----------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|
| <b>Delaware</b>                              | <b>1</b>  | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>   | <b>4</b>   | <b>8</b>   | <b>11</b>  | <b>11</b>  | <b>13</b>  | <b>14</b>  | <b>13</b>  | <b>15</b>  | <b>10</b>  | <b>10</b>  |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   |
| Smart Start 2020                             | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 1          | 1          | 0          | 1          | 1          | 1          |
| Smart Start SS1-1000                         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>   | <b>1</b>   | <b>3</b>   | <b>5</b>   | <b>6</b>   | <b>6</b>   | <b>7</b>   | <b>7</b>   | <b>8</b>   | <b>3</b>   | <b>3</b>   |
| Intoxalock 1001A                             | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 1          | 3          | 5          | 6          | 6          | 7          | 7          | 7          | 2          | 2          |
| Intoxalock 1001A Advanced                    | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 1          | 1          | 1          |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Draeger XT                                   | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>   | <b>1</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   |
| Interceptor M-1                              | 1         | 1         | 1         | 1         | 1         | 1         | 1          | 1          | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 2          |
| <b>National Interlock Service LTD</b>        | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>2</b>   | <b>2</b>   | <b>3</b>   | <b>3</b>   | <b>3</b>   | <b>3</b>   | <b>3</b>   | <b>3</b>   |
| LifeSafer FC100 camera                       | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 2          |
| LifeSafer FC100 no camera                    | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 1          | 1          | 1          | 1          | 1          | 1          |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>   | <b>2</b>   | <b>3</b>   | <b>2</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   |
| Best Labs FR9000                             |           | 1         | 2         | 2         | 2         | 2         | 2          | 2          | 3          | 2          | 1          | 1          | 1          | 1          | 1          | 1          | 1          |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |           |           |           |           |           |            |            |            |            |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Alcohol Detection Systems DM-904             |           |           |           |           |           |           |            |            |            |            |            | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Dutchess</b>                              | <b>16</b> | <b>22</b> | <b>27</b> | <b>57</b> | <b>80</b> | <b>97</b> | <b>109</b> | <b>134</b> | <b>143</b> | <b>170</b> | <b>184</b> | <b>196</b> | <b>201</b> | <b>197</b> | <b>192</b> | <b>199</b> | <b>160</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>5</b>  | <b>8</b>  | <b>14</b> | <b>39</b> | <b>51</b> | <b>60</b> | <b>69</b>  | <b>93</b>  | <b>103</b> | <b>110</b> | <b>118</b> | <b>119</b> | <b>110</b> | <b>102</b> | <b>89</b>  | <b>89</b>  | <b>78</b>  |
| Smart Start 2020                             | 5         | 8         | 14        | 39        | 51        | 60        | 69         | 93         | 102        | 109        | 117        | 119        | 110        | 102        | 89         | 89         | 78         |
| Smart Start SS1-1000                         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 1          | 1          | 1          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>2</b>  | <b>3</b>  | <b>4</b>  | <b>9</b>  | <b>11</b> | <b>11</b>  | <b>11</b>  | <b>10</b>  | <b>14</b>  | <b>14</b>  | <b>16</b>  | <b>16</b>  | <b>18</b>  | <b>18</b>  | <b>21</b>  | <b>18</b>  |
| Intoxalock 1001A                             | 0         | 0         | 0         | 0         | 1         | 1         | 1          | 1          | 1          | 3          | 2          | 2          | 2          | 2          | 2          | 1          | 1          |
| Intoxalock 1001A Advanced                    | 0         | 2         | 3         | 4         | 8         | 10        | 10         | 10         | 9          | 11         | 12         | 14         | 14         | 16         | 16         | 20         | 17         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Draeger XT                                   | 1         | 1         | 1         | 1         | 1         | 1         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>6</b>  | <b>5</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>   | <b>5</b>   | <b>5</b>   | <b>5</b>   | <b>5</b>   | <b>5</b>   | <b>5</b>   | <b>5</b>   | <b>4</b>   | <b>5</b>   | <b>4</b>   |
| Interceptor M-1                              | 6         | 5         | 4         | 4         | 4         | 4         | 4          | 5          | 5          | 5          | 5          | 5          | 5          | 5          | 4          | 5          | 4          |
| <b>National Interlock Service LTD</b>        | <b>4</b>  | <b>5</b>  | <b>4</b>  | <b>6</b>  | <b>12</b> | <b>18</b> | <b>21</b>  | <b>21</b>  | <b>21</b>  | <b>37</b>  | <b>44</b>  | <b>54</b>  | <b>68</b>  | <b>71</b>  | <b>80</b>  | <b>83</b>  | <b>59</b>  |
| LifeSafer FC100 camera                       | 0         | 0         | 0         | 0         | 4         | 8         | 12         | 13         | 13         | 33         | 40         | 50         | 65         | 67         | 74         | 77         | 55         |
| LifeSafer FC100 no camera                    | 4         | 5         | 4         | 6         | 8         | 10        | 9          | 8          | 8          | 4          | 4          | 4          | 3          | 4          | 6          | 6          | 4          |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>1</b>  | <b>1</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>4</b>   | <b>4</b>   | <b>4</b>   | <b>4</b>   | <b>3</b>   | <b>2</b>   | <b>2</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   |
| Best Labs FR9000                             |           | 1         | 1         | 3         | 3         | 3         | 4          | 4          | 4          | 4          | 3          | 2          | 2          | 1          | 1          | 1          | 1          |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |           |           |           |           |           |            |            |            |            |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Alcohol Detection Systems DM-904             |           |           |           |           |           |           |            |            |            |            |            | 0          | 0          | 0          | 0          | 0          | 0          |

|  |            |            |            |            |            |            |            |            |            |            |            |            |            |            |            |            |            |
|--|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|
| <b>Erie</b>                                  | <b>183</b> | <b>212</b> | <b>259</b> | <b>287</b> | <b>317</b> | <b>364</b> | <b>400</b> | <b>427</b> | <b>434</b> | <b>464</b> | <b>461</b> | <b>468</b> | <b>480</b> | <b>490</b> | <b>477</b> | <b>477</b> | <b>457</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>19</b>  | <b>20</b>  | <b>30</b>  | <b>34</b>  | <b>44</b>  | <b>51</b>  | <b>56</b>  | <b>58</b>  | <b>64</b>  | <b>70</b>  | <b>86</b>  | <b>87</b>  | <b>87</b>  | <b>88</b>  | <b>86</b>  | <b>86</b>  | <b>75</b>  |
| Smart Start 2020                             | 5          | 9          | 20         | 25         | 36         | 43         | 50         | 52         | 60         | 66         | 83         | 84         | 84         | 85         | 83         | 83         | 72         |
| Smart Start SS1-1000                         | 14         | 11         | 10         | 9          | 8          | 8          | 6          | 6          | 4          | 4          | 3          | 3          | 3          | 3          | 3          | 3          | 3          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>   | <b>3</b>   | <b>6</b>   | <b>9</b>   | <b>9</b>   | <b>12</b>  | <b>14</b>  | <b>16</b>  | <b>16</b>  | <b>19</b>  | <b>20</b>  | <b>30</b>  | <b>30</b>  | <b>33</b>  | <b>37</b>  | <b>38</b>  | <b>35</b>  |
| Intoxalock 1001A                             | 0          | 2          | 5          | 8          | 8          | 11         | 13         | 15         | 16         | 19         | 20         | 30         | 30         | 33         | 36         | 37         | 34         |
| Intoxalock 1001A Advanced                    | 0          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 0          | 0          | 0          | 0          | 0          | 0          | 1          | 1          | 1          |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>141</b> | <b>160</b> | <b>183</b> | <b>203</b> | <b>225</b> | <b>261</b> | <b>287</b> | <b>313</b> | <b>313</b> | <b>334</b> | <b>312</b> | <b>306</b> | <b>316</b> | <b>323</b> | <b>312</b> | <b>307</b> | <b>302</b> |
| Draeger XT                                   | 141        | 160        | 183        | 203        | 225        | 261        | 287        | 313        | 313        | 334        | 312        | 306        | 316        | 323        | 312        | 307        | 302        |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Interceptor M-1                              | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>National Interlock Service LTD</b>        | <b>23</b>  | <b>24</b>  | <b>30</b>  | <b>28</b>  | <b>25</b>  | <b>26</b>  | <b>26</b>  | <b>21</b>  | <b>21</b>  | <b>20</b>  | <b>20</b>  | <b>22</b>  | <b>24</b>  | <b>25</b>  | <b>23</b>  | <b>27</b>  | <b>25</b>  |
| LifeSafer FC100 camera                       | 0          | 0          | 0          | 0          | 0          | 0          | 1          | 1          | 1          | 0          | 0          | 0          | 0          | 0          | 0          | 2          | 2          |
| LifeSafer FC100 no camera                    | 23         | 24         | 30         | 28         | 25         | 26         | 25         | 20         | 20         | 20         | 20         | 22         | 24         | 25         | 23         | 25         | 23         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |            | <b>5</b>   | <b>10</b>  | <b>13</b>  | <b>14</b>  | <b>14</b>  | <b>17</b>  | <b>19</b>  | <b>20</b>  | <b>21</b>  | <b>23</b>  | <b>23</b>  | <b>23</b>  | <b>21</b>  | <b>19</b>  | <b>19</b>  | <b>19</b>  |
| Best Labs FR9000                             |            | 5          | 10         | 13         | 14         | 14         | 17         | 19         | 20         | 21         | 23         | 23         | 23         | 21         | 19         | 19         | 19         |
| <b>Statewide Interlock Systemes, Inc.</b>    |            |            |            |            |            |            |            |            |            |            |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>1</b>   |
| Alcohol Detection Systems DM-904             |            |            |            |            |            |            |            |            |            |            |            | 0          | 0          | 0          | 0          | 0          | 1          |
| <b>Essex</b>                                 | <b>1</b>   | <b>1</b>   | <b>2</b>   | <b>2</b>   | <b>5</b>   | <b>5</b>   | <b>5</b>   | <b>6</b>   | <b>6</b>   | <b>9</b>   | <b>11</b>  | <b>14</b>  | <b>14</b>  | <b>15</b>  | <b>15</b>  | <b>18</b>  | <b>17</b>  |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>3</b>   | <b>3</b>   | <b>3</b>   | <b>4</b>   |
| Smart Start 2020                             | 0          | 0          | 0          | 0          | 1          | 1          | 1          | 1          | 1          | 2          | 2          | 2          | 2          | 3          | 3          | 3          | 4          |
| Smart Start SS1-1000                         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>3</b>   | <b>3</b>   | <b>4</b>   | <b>6</b>   | <b>9</b>   | <b>9</b>   | <b>9</b>   | <b>9</b>   | <b>12</b>  | <b>10</b>  |
| Intoxalock 1001A                             | 0          | 0          | 0          | 0          | 1          | 1          | 1          | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 1          | 1          | 0          |
| Intoxalock 1001A Advanced                    | 0          | 0          | 0          | 0          | 1          | 1          | 1          | 1          | 1          | 2          | 4          | 7          | 7          | 7          | 8          | 11         | 10         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Draeger XT                                   | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>1</b>   | <b>1</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   |
| Interceptor M-1                              | 1          | 1          | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 2          |
| <b>National Interlock Service LTD</b>        | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   |
| LifeSafer FC100 camera                       | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 1          | 1          | 0          | 0          | 0          | 0          | 0          | 0          |
| LifeSafer FC100 no camera                    | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 1          | 1          | 1          | 1          | 1          | 1          |
| <b>Sens_O-Lock of America, L.L.C.</b>        |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Best Labs FR9000                             |            | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Statewide Interlock Systemes, Inc.</b>    |            |            |            |            |            |            |            |            |            |            |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Alcohol Detection Systems DM-904             |            |            |            |            |            |            |            |            |            |            |            | 0          | 0          | 0          | 0          | 0          | 0          |



|  |          |          |          |          |          |          |          |          |           |           |           |           |           |           |          |           |           |
|--|----------|----------|----------|----------|----------|----------|----------|----------|-----------|-----------|-----------|-----------|-----------|-----------|----------|-----------|-----------|
| <b>Franklin</b>                              | <b>1</b> | <b>2</b> | <b>2</b> | <b>5</b> | <b>5</b> | <b>7</b> | <b>8</b> | <b>8</b> | <b>11</b> | <b>11</b> | <b>9</b>  | <b>9</b>  | <b>9</b>  | <b>8</b>  | <b>8</b> | <b>10</b> | <b>14</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>0</b> | <b>0</b> | <b>1</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b> | <b>1</b>  | <b>3</b>  |
| Smart Start 2020                             | 0        | 0        | 0        | 1        | 0        | 0        | 0        | 0        | 1         | 1         | 1         | 1         | 1         | 1         | 1        | 1         | 3         |
| Smart Start SS1-1000                         | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0        | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>1</b> | <b>1</b> | <b>3</b> | <b>3</b> | <b>5</b> | <b>6</b> | <b>6</b> | <b>8</b>  | <b>8</b>  | <b>6</b>  | <b>6</b>  | <b>6</b>  | <b>5</b>  | <b>5</b> | <b>7</b>  | <b>9</b>  |
| Intoxalock 1001A                             | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0        | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0        | 1        | 1        | 3        | 3        | 5        | 6        | 6        | 8         | 8         | 6         | 6         | 6         | 5         | 5        | 7         | 9         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b> | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0        | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>2</b> | <b>2</b> | <b>2</b> | <b>2</b> | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b> | <b>2</b>  | <b>2</b>  |
| Interceptor M-1                              | 1        | 1        | 1        | 1        | 2        | 2        | 2        | 2        | 2         | 2         | 2         | 2         | 2         | 2         | 2        | 2         | 2         |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b> | <b>0</b>  | <b>0</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0        | 0         | 0         |
| LifeSafer FC100 no camera                    | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0        | 0         | 0         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b> | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0        | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |          |          |          |          |          |          |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b> | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |          |          |          |          |          |          |           |           | 0         | 0         | 0         | 0         | 0        | 0         | 0         |
| <b>Fulton</b>                                | <b>2</b> | <b>2</b> | <b>3</b> | <b>5</b> | <b>5</b> | <b>6</b> | <b>6</b> | <b>8</b> | <b>10</b> | <b>11</b> | <b>11</b> | <b>12</b> | <b>11</b> | <b>10</b> | <b>5</b> | <b>7</b>  | <b>11</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>0</b> | <b>1</b> | <b>2</b> | <b>2</b> | <b>2</b> | <b>2</b> | <b>5</b> | <b>6</b>  | <b>6</b>  | <b>6</b>  | <b>6</b>  | <b>5</b>  | <b>4</b>  | <b>0</b> | <b>0</b>  | <b>2</b>  |
| Smart Start 2020                             | 0        | 0        | 1        | 2        | 2        | 2        | 2        | 5        | 6         | 6         | 6         | 6         | 5         | 4         | 0        | 0         | 2         |
| Smart Start SS1-1000                         | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0        | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>1</b> | <b>3</b>  | <b>5</b>  |
| Intoxalock 1001A                             | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0        | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0        | 0        | 0        | 0        | 0        | 1        | 1        | 1        | 2         | 2         | 2         | 2         | 2         | 2         | 1        | 3         | 5         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b> | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0        | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>2</b> | <b>2</b> | <b>2</b> | <b>2</b> | <b>2</b> | <b>2</b> | <b>2</b> | <b>1</b> | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b> | <b>1</b>  | <b>1</b>  |
| Interceptor M-1                              | 2        | 2        | 2        | 2        | 2        | 2        | 2        | 1        | 1         | 1         | 1         | 1         | 1         | 1         | 1        | 1         | 1         |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>0</b> | <b>0</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>3</b> | <b>3</b>  | <b>3</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0        | 1        | 1        | 1        | 1        | 1        | 1         | 1         | 1         | 2         | 2         | 2         | 2        | 2         | 2         |
| LifeSafer FC100 no camera                    | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 1         | 1         | 1         | 1         | 1         | 1        | 1         | 1         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b> | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0        | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |          |          |          |          |          |          |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b> | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |          |          |          |          |          |          |           |           | 0         | 0         | 0         | 0         | 0        | 0         | 0         |

|  |          |          |          |           |           |           |           |           |           |           |           |           |           |           |           |           |           |
|--|----------|----------|----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| <b>Genesee</b>                               | <b>1</b> | <b>1</b> | <b>5</b> | <b>10</b> | <b>16</b> | <b>21</b> | <b>26</b> | <b>26</b> | <b>30</b> | <b>34</b> | <b>44</b> | <b>51</b> | <b>50</b> | <b>55</b> | <b>52</b> | <b>55</b> | <b>53</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>0</b> | <b>3</b> | <b>6</b>  | <b>7</b>  | <b>11</b> | <b>15</b> | <b>15</b> | <b>16</b> | <b>17</b> | <b>23</b> | <b>27</b> | <b>26</b> | <b>31</b> | <b>28</b> | <b>28</b> | <b>28</b> |
| Smart Start 2020                             | 0        | 0        | 3        | 6         | 7         | 11        | 15        | 15        | 16        | 17        | 23        | 27        | 26        | 31        | 28        | 28        | 28        |
| Smart Start SS1-1000                         | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>1</b>  | <b>4</b>  | <b>4</b>  | <b>5</b>  | <b>5</b>  | <b>7</b>  | <b>9</b>  | <b>12</b> | <b>17</b> | <b>18</b> | <b>19</b> | <b>19</b> | <b>22</b> | <b>21</b> |
| Intoxalock 1001A                             | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0        | 0        | 0        | 1         | 4         | 4         | 5         | 5         | 7         | 9         | 12        | 17        | 18        | 19        | 19        | 22        | 21        |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>1</b> | <b>1</b> | <b>1</b> | <b>2</b>  | <b>3</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>5</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>2</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  |
| Draeger XT                                   | 1        | 1        | 1        | 2         | 3         | 4         | 4         | 4         | 5         | 4         | 4         | 4         | 2         | 1         | 1         | 1         | 1         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  |
| Interceptor M-1                              | 0        | 0        | 0        | 0         | 1         | 1         | 1         | 1         | 1         | 1         | 2         | 1         | 2         | 2         | 2         | 2         | 2         |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>1</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 2         | 0         | 0         | 1         | 0         | 1         | 0         |
| LifeSafer FC100 no camera                    | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 0         | 2         | 2         | 1         | 2         | 1         | 1         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b> | <b>1</b> | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0        | 1        | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |          |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |          |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Greene</b>                                | <b>1</b> | <b>2</b> | <b>2</b> | <b>3</b>  | <b>9</b>  | <b>11</b> | <b>12</b> | <b>10</b> | <b>12</b> | <b>16</b> | <b>18</b> | <b>19</b> | <b>20</b> | <b>22</b> | <b>21</b> | <b>21</b> | <b>23</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  |
| Smart Start 2020                             | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         |
| Smart Start SS1-1000                         | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>1</b>  | <b>5</b>  | <b>7</b>  | <b>8</b>  | <b>8</b>  | <b>10</b> | <b>11</b> | <b>11</b> | <b>15</b> | <b>15</b> | <b>17</b> | <b>17</b> | <b>17</b> | <b>19</b> |
| Intoxalock 1001A                             | 0        | 0        | 0        | 1         | 2         | 2         | 2         | 2         | 3         | 3         | 2         | 1         | 1         | 1         | 1         | 1         | 1         |
| Intoxalock 1001A Advanced                    | 0        | 0        | 0        | 0         | 3         | 5         | 6         | 6         | 7         | 8         | 9         | 14        | 14        | 16        | 16        | 16        | 18        |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  |
| Interceptor M-1                              | 1        | 1        | 1        | 1         | 2         | 2         | 2         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  | <b>3</b>  | <b>5</b>  | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0        | 0         | 1         | 1         | 1         | 0         | 0         | 1         | 2         | 2         | 3         | 3         | 2         | 2         | 2         |
| LifeSafer FC100 no camera                    | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 2         | 3         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>1</b> | <b>1</b> | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 1        | 1        | 1         | 1         | 1         | 1         | 1         | 1         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |          |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |          |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |

|  |          |          |          |          |          |          |          |          |           |           |           |           |           |           |           |           |           |
|--|----------|----------|----------|----------|----------|----------|----------|----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| <b>Hamilton</b>                              | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>3</b>  |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Smart Start 2020                             | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| Smart Start SS1-1000                         | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Intoxalock 1001A                             | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>3</b>  |
| Interceptor M-1                              | 1        | 1        | 1        | 1        | 1        | 1        | 1        | 1        | 1         | 1         | 2         | 2         | 2         | 2         | 2         | 2         | 3         |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| LifeSafer FC100 no camera                    | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |          |          |          |          |          |          |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |          |          |          |          |          |          |           |           | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Herkimer</b>                              | <b>0</b> | <b>0</b> | <b>2</b> | <b>2</b> | <b>2</b> | <b>6</b> | <b>6</b> | <b>7</b> | <b>10</b> | <b>11</b> | <b>13</b> | <b>14</b> | <b>17</b> | <b>17</b> | <b>16</b> | <b>16</b> | <b>18</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>0</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>5</b> | <b>5</b> | <b>6</b> | <b>8</b>  | <b>9</b>  | <b>10</b> | <b>11</b> | <b>13</b> | <b>12</b> | <b>10</b> | <b>10</b> | <b>10</b> |
| Smart Start 2020                             | 0        | 0        | 1        | 1        | 1        | 5        | 5        | 6        | 8         | 9         | 10        | 11        | 13        | 12        | 10        | 10        | 10        |
| Smart Start SS1-1000                         | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>0</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>3</b>  | <b>4</b>  | <b>5</b>  | <b>5</b>  | <b>7</b>  |
| Intoxalock 1001A                             | 0        | 0        | 1        | 1        | 1        | 1        | 1        | 1        | 1         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 1         | 2         | 2         | 3         | 4         | 5         | 5         | 7         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  |
| Interceptor M-1                              | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| LifeSafer FC100 no camera                    | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0        | 0        | 0        | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |          |          |          |          |          |          |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |          |          |          |          |          |          |           |           | 0         | 0         | 0         | 0         | 0         | 0         | 0         |

|  |           |           |           |           |           |           |           |           |           |           |           |           |           |           |           |           |           |
|--|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| <b>Jefferson</b>                             | <b>18</b> | <b>20</b> | <b>26</b> | <b>29</b> | <b>34</b> | <b>40</b> | <b>51</b> | <b>62</b> | <b>61</b> | <b>64</b> | <b>76</b> | <b>80</b> | <b>84</b> | <b>84</b> | <b>92</b> | <b>94</b> | <b>89</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>2</b>  | <b>2</b>  | <b>8</b>  | <b>11</b> | <b>14</b> | <b>20</b> | <b>29</b> | <b>36</b> | <b>35</b> | <b>38</b> | <b>47</b> | <b>50</b> | <b>52</b> | <b>50</b> | <b>59</b> | <b>59</b> | <b>51</b> |
| Smart Start 2020                             | 2         | 2         | 8         | 11        | 14        | 20        | 29        | 36        | 35        | 38        | 47        | 50        | 52        | 50        | 59        | 59        | 51        |
| Smart Start SS1-1000                         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>3</b>  | <b>4</b>  | <b>5</b>  | <b>6</b>  | <b>7</b>  | <b>9</b>  | <b>9</b>  |
| Intoxalock 1001A                             | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 3         | 4         | 5         | 6         | 7         | 9         | 9         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>16</b> | <b>17</b> | <b>17</b> | <b>17</b> | <b>19</b> | <b>19</b> | <b>21</b> | <b>25</b> | <b>25</b> | <b>25</b> | <b>26</b> | <b>26</b> | <b>26</b> | <b>27</b> | <b>25</b> | <b>25</b> | <b>27</b> |
| Interceptor M-1                              | 16        | 17        | 17        | 17        | 19        | 19        | 21        | 25        | 25        | 25        | 26        | 26        | 26        | 27        | 25        | 25        | 27        |
| <b>National Interlock Service LTD</b>        | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  |
| LifeSafer FC100 camera                       | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 2         |
| LifeSafer FC100 no camera                    | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |           | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |           |           |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |           |           |           |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Kings</b>                                 | <b>1</b>  | <b>9</b>  | <b>10</b> | <b>11</b> | <b>11</b> | <b>15</b> | <b>28</b> | <b>31</b> | <b>39</b> | <b>39</b> | <b>42</b> | <b>55</b> | <b>57</b> | <b>52</b> | <b>58</b> | <b>63</b> | <b>64</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>  | <b>3</b>  | <b>5</b>  | <b>5</b>  | <b>4</b>  | <b>4</b>  | <b>10</b> | <b>12</b> | <b>15</b> | <b>16</b> | <b>19</b> | <b>23</b> | <b>23</b> | <b>21</b> | <b>25</b> | <b>25</b> | <b>30</b> |
| Smart Start 2020                             | 0         | 3         | 5         | 5         | 4         | 4         | 10        | 12        | 15        | 16        | 19        | 23        | 23        | 21        | 25        | 25        | 30        |
| Smart Start SS1-1000                         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>2</b>  | <b>4</b>  | <b>6</b>  | <b>7</b>  | <b>6</b>  | <b>6</b>  | <b>8</b>  | <b>10</b> | <b>12</b> | <b>12</b> | <b>12</b> | <b>13</b> | <b>13</b> |
| Intoxalock 1001A                             | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0         | 0         | 0         | 0         | 2         | 4         | 6         | 7         | 6         | 6         | 8         | 10        | 12        | 12        | 12        | 13        | 13        |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>2</b>  | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>4</b>  | <b>4</b>  |
| Interceptor M-1                              | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 2         | 2         | 3         | 3         | 3         | 3         | 4         | 4         |
| <b>National Interlock Service LTD</b>        | <b>1</b>  | <b>3</b>  | <b>3</b>  | <b>4</b>  | <b>4</b>  | <b>6</b>  | <b>11</b> | <b>11</b> | <b>17</b> | <b>14</b> | <b>12</b> | <b>18</b> | <b>19</b> | <b>16</b> | <b>18</b> | <b>21</b> | <b>17</b> |
| LifeSafer FC100 camera                       | 0         | 0         | 0         | 1         | 1         | 3         | 8         | 8         | 14        | 13        | 12        | 16        | 17        | 15        | 17        | 20        | 16        |
| LifeSafer FC100 no camera                    | 1         | 3         | 3         | 3         | 3         | 3         | 3         | 3         | 3         | 1         | 0         | 2         | 2         | 1         | 1         | 1         | 1         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>3</b>  | <b>2</b>  | <b>2</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |           | 3         | 2         | 2         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 0         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |           |           |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |           |           |           |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |

|  |          |          |           |           |           |           |           |           |           |           |           |           |           |           |           |           |           |
|--|----------|----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| <b>Lewis</b>                                 | <b>4</b> | <b>4</b> | <b>4</b>  | <b>5</b>  | <b>4</b>  | <b>5</b>  | <b>6</b>  | <b>8</b>  | <b>10</b> | <b>9</b>  | <b>9</b>  | <b>9</b>  | <b>8</b>  | <b>9</b>  | <b>8</b>  | <b>8</b>  | <b>14</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>0</b> | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>2</b>  | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>6</b>  |
| Smart Start 2020                             | 0        | 0        | 0         | 1         | 1         | 1         | 1         | 2         | 3         | 3         | 3         | 2         | 2         | 3         | 3         | 3         | 6         |
| Smart Start SS1-1000                         | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>4</b>  |
| Intoxalock 1001A                             | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 1         | 4         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>4</b> | <b>4</b> | <b>4</b>  | <b>4</b>  | <b>3</b>  | <b>4</b>  | <b>4</b>  | <b>5</b>  | <b>5</b>  | <b>5</b>  | <b>5</b>  | <b>5</b>  | <b>5</b>  | <b>5</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  |
| Interceptor M-1                              | 4        | 4        | 4         | 4         | 3         | 4         | 4         | 5         | 5         | 5         | 5         | 5         | 5         | 5         | 4         | 4         | 4         |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| LifeSafer FC100 no camera                    | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0        | 0         | 0         | 0         | 0         | 1         | 1         | 2         | 1         | 1         | 1         | 0         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |           |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |           |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Livingston</b>                            | <b>2</b> | <b>3</b> | <b>12</b> | <b>21</b> | <b>25</b> | <b>30</b> | <b>33</b> | <b>39</b> | <b>36</b> | <b>42</b> | <b>44</b> | <b>51</b> | <b>55</b> | <b>54</b> | <b>57</b> | <b>59</b> | <b>57</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>1</b> | <b>9</b>  | <b>18</b> | <b>21</b> | <b>23</b> | <b>26</b> | <b>31</b> | <b>28</b> | <b>30</b> | <b>32</b> | <b>34</b> | <b>38</b> | <b>39</b> | <b>40</b> | <b>40</b> | <b>40</b> |
| Smart Start 2020                             | 0        | 1        | 9         | 18        | 21        | 23        | 26        | 31        | 28        | 30        | 32        | 34        | 38        | 39        | 40        | 40        | 40        |
| Smart Start SS1-1000                         | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>0</b> | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>5</b>  | <b>5</b>  | <b>6</b>  | <b>8</b>  | <b>11</b> | <b>9</b>  |
| Intoxalock 1001A                             | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0        | 0        | 1         | 1         | 2         | 2         | 2         | 3         | 3         | 3         | 3         | 5         | 5         | 6         | 8         | 11        | 9         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>2</b> | <b>2</b> | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>5</b>  | <b>5</b>  | <b>5</b>  | <b>5</b>  | <b>6</b>  | <b>6</b>  | <b>6</b>  | <b>5</b>  | <b>2</b>  | <b>2</b>  | <b>1</b>  | <b>0</b>  |
| Draeger XT                                   | 2        | 2        | 2         | 2         | 2         | 5         | 5         | 5         | 5         | 6         | 6         | 6         | 5         | 2         | 2         | 1         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  |
| Interceptor M-1                              | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 1         | 1         |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>3</b>  | <b>3</b>  | <b>5</b>  | <b>6</b>  | <b>6</b>  | <b>6</b>  | <b>6</b>  | <b>7</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 3         | 3         | 5         | 6         | 6         | 6         | 6         | 7         |
| LifeSafer FC100 no camera                    | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |           |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |           |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |

|  |            |            |            |            |            |            |            |            |            |            |            |            |            |            |            |            |            |
|--|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|
| <b>Madison</b>                               | <b>3</b>   | <b>4</b>   | <b>5</b>   | <b>9</b>   | <b>12</b>  | <b>12</b>  | <b>14</b>  | <b>17</b>  | <b>21</b>  | <b>27</b>  | <b>28</b>  | <b>28</b>  | <b>28</b>  | <b>29</b>  | <b>26</b>  | <b>27</b>  | <b>28</b>  |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>1</b>   | <b>3</b>   | <b>3</b>   | <b>4</b>   | <b>5</b>   | <b>7</b>   | <b>7</b>   | <b>6</b>   | <b>7</b>   | <b>7</b>   | <b>5</b>   | <b>4</b>   | <b>4</b>   | <b>4</b>   |
| Smart Start 2020                             | 0          | 0          | 0          | 1          | 3          | 3          | 4          | 5          | 7          | 7          | 6          | 7          | 7          | 5          | 4          | 4          | 4          |
| Smart Start SS1-1000                         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>3</b>   | <b>2</b>   | <b>3</b>   | <b>2</b>   |
| Intoxalock 1001A                             | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| Intoxalock 1001A Advanced                    | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 1          | 1          | 1          | 2          | 2          | 2          | 3          | 2          | 3          | 2          |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Draeger XT                                   | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>3</b>   | <b>4</b>   | <b>5</b>   | <b>8</b>   | <b>9</b>   | <b>9</b>   | <b>10</b>  | <b>11</b>  | <b>13</b>  | <b>15</b>  | <b>15</b>  | <b>15</b>  | <b>17</b>  | <b>18</b>  | <b>18</b>  | <b>18</b>  | <b>20</b>  |
| Interceptor M-1                              | 3          | 4          | 5          | 8          | 9          | 9          | 10         | 11         | 13         | 15         | 15         | 15         | 17         | 18         | 18         | 18         | 20         |
| <b>National Interlock Service LTD</b>        | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>4</b>   | <b>5</b>   | <b>4</b>   | <b>2</b>   | <b>3</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   |
| LifeSafer FC100 camera                       | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 2          | 3          | 2          | 1          | 1          | 1          | 1          | 1          |
| LifeSafer FC100 no camera                    | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 2          | 2          | 2          | 1          | 2          | 1          | 1          | 1          |
| <b>Sens_O-Lock of America, L.L.C.</b>        |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Best Labs FR9000                             |            | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Statewide Interlock Systemes, Inc.</b>    |            |            |            |            |            |            |            |            |            |            |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Alcohol Detection Systems DM-904             |            |            |            |            |            |            |            |            |            |            |            | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Monroe</b>                                | <b>120</b> | <b>112</b> | <b>126</b> | <b>146</b> | <b>173</b> | <b>212</b> | <b>260</b> | <b>289</b> | <b>322</b> | <b>346</b> | <b>375</b> | <b>402</b> | <b>391</b> | <b>409</b> | <b>423</b> | <b>446</b> | <b>455</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>4</b>   | <b>4</b>   | <b>14</b>  | <b>28</b>  | <b>43</b>  | <b>70</b>  | <b>96</b>  | <b>120</b> | <b>142</b> | <b>162</b> | <b>185</b> | <b>197</b> | <b>194</b> | <b>209</b> | <b>216</b> | <b>216</b> | <b>211</b> |
| Smart Start 2020                             | 4          | 4          | 14         | 28         | 43         | 70         | 96         | 120        | 142        | 162        | 185        | 197        | 194        | 209        | 216        | 216        | 211        |
| Smart Start SS1-1000                         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>   | <b>0</b>   | <b>1</b>   | <b>5</b>   | <b>10</b>  | <b>19</b>  | <b>26</b>  | <b>31</b>  | <b>38</b>  | <b>40</b>  | <b>45</b>  | <b>61</b>  | <b>62</b>  | <b>71</b>  | <b>83</b>  | <b>102</b> | <b>114</b> |
| Intoxalock 1001A                             | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 1          | 1          | 1          | 2          | 2          | 2          |
| Intoxalock 1001A Advanced                    | 0          | 0          | 1          | 5          | 10         | 19         | 26         | 31         | 38         | 40         | 45         | 60         | 61         | 70         | 81         | 100        | 112        |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>111</b> | <b>98</b>  | <b>99</b>  | <b>96</b>  | <b>98</b>  | <b>94</b>  | <b>104</b> | <b>106</b> | <b>106</b> | <b>101</b> | <b>92</b>  | <b>82</b>  | <b>73</b>  | <b>65</b>  | <b>56</b>  | <b>59</b>  | <b>62</b>  |
| Draeger XT                                   | 111        | 98         | 99         | 96         | 98         | 94         | 104        | 106        | 106        | 101        | 92         | 82         | 73         | 65         | 56         | 59         | 62         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>3</b>   | <b>3</b>   | <b>4</b>   | <b>4</b>   | <b>6</b>   | <b>6</b>   | <b>7</b>   | <b>9</b>   | <b>13</b>  | <b>18</b>  | <b>26</b>  | <b>31</b>  | <b>31</b>  | <b>35</b>  | <b>38</b>  | <b>40</b>  | <b>38</b>  |
| Interceptor M-1                              | 3          | 3          | 4          | 4          | 6          | 6          | 7          | 9          | 13         | 18         | 26         | 31         | 31         | 35         | 38         | 40         | 38         |
| <b>National Interlock Service LTD</b>        | <b>2</b>   | <b>7</b>   | <b>8</b>   | <b>12</b>  | <b>15</b>  | <b>22</b>  | <b>26</b>  | <b>22</b>  | <b>22</b>  | <b>24</b>  | <b>26</b>  | <b>30</b>  | <b>31</b>  | <b>29</b>  | <b>30</b>  | <b>29</b>  | <b>30</b>  |
| LifeSafer FC100 camera                       | 0          | 0          | 1          | 2          | 4          | 6          | 8          | 7          | 8          | 14         | 20         | 20         | 23         | 24         | 25         | 25         | 29         |
| LifeSafer FC100 no camera                    | 2          | 7          | 7          | 10         | 11         | 16         | 18         | 15         | 14         | 10         | 6          | 10         | 8          | 5          | 5          | 4          | 1          |
| <b>Sens_O-Lock of America, L.L.C.</b>        |            | <b>0</b>   | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Best Labs FR9000                             |            | 0          | 0          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 0          | 0          | 0          | 0          | 0          |
| <b>Statewide Interlock Systemes, Inc.</b>    |            |            |            |            |            |            |            |            |            |            |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Alcohol Detection Systems DM-904             |            |            |            |            |            |            |            |            |            |            |            | 0          | 0          | 0          | 0          | 0          | 0          |

|  |            |            |            |            |            |            |            |            |             |             |             |             |             |             |             |             |             |
|--|------------|------------|------------|------------|------------|------------|------------|------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|
| <b>Montgomery</b>                            | <b>8</b>   | <b>9</b>   | <b>10</b>  | <b>12</b>  | <b>13</b>  | <b>14</b>  | <b>14</b>  | <b>17</b>  | <b>17</b>   | <b>19</b>   | <b>20</b>   | <b>23</b>   | <b>25</b>   | <b>23</b>   | <b>24</b>   | <b>23</b>   | <b>21</b>   |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>2</b>   | <b>2</b>   | <b>3</b>   | <b>3</b>    | <b>5</b>    | <b>5</b>    | <b>7</b>    | <b>7</b>    | <b>7</b>    | <b>7</b>    | <b>7</b>    | <b>6</b>    |
| Smart Start 2020                             | 0          | 0          | 0          | 1          | 1          | 2          | 2          | 3          | 3           | 5           | 5           | 7           | 7           | 7           | 7           | 7           | 6           |
| Smart Start SS1-1000                         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>   | <b>0</b>   | <b>1</b>   | <b>2</b>   | <b>5</b>   | <b>5</b>   | <b>5</b>   | <b>6</b>   | <b>6</b>    | <b>6</b>    | <b>7</b>    | <b>8</b>    | <b>8</b>    | <b>7</b>    | <b>8</b>    | <b>5</b>    | <b>4</b>    |
| Intoxalock 1001A                             | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           |
| Intoxalock 1001A Advanced                    | 0          | 0          | 1          | 2          | 5          | 5          | 5          | 6          | 6           | 6           | 7           | 8           | 8           | 7           | 8           | 5           | 4           |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    |
| Draeger XT                                   | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>8</b>   | <b>8</b>   | <b>8</b>   | <b>8</b>   | <b>6</b>   | <b>6</b>   | <b>6</b>   | <b>7</b>   | <b>7</b>    | <b>7</b>    | <b>7</b>    | <b>7</b>    | <b>9</b>    | <b>8</b>    | <b>8</b>    | <b>9</b>    | <b>9</b>    |
| Interceptor M-1                              | 8          | 8          | 8          | 8          | 6          | 6          | 6          | 7          | 7           | 7           | 7           | 7           | 9           | 8           | 8           | 9           | 9           |
| <b>National Interlock Service LTD</b>        | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>2</b>    | <b>2</b>    |
| LifeSafer FC100 camera                       | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 1           | 1           |
| LifeSafer FC100 no camera                    | 0          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1           | 1           | 1           | 1           | 1           | 1           | 1           | 1           | 1           |
| <b>Sens_O-Lock of America, L.L.C.</b>        |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    |
| Best Labs FR9000                             |            | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           |
| <b>Statewide Interlock Systemes, Inc.</b>    |            |            |            |            |            |            |            |            |             |             |             | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    |
| Alcohol Detection Systems DM-904             |            |            |            |            |            |            |            |            |             |             |             | 0           | 0           | 0           | 0           | 0           | 0           |
| <b>Nassau</b>                                | <b>775</b> | <b>790</b> | <b>821</b> | <b>844</b> | <b>873</b> | <b>893</b> | <b>940</b> | <b>965</b> | <b>1014</b> | <b>1013</b> | <b>1030</b> | <b>1028</b> | <b>1016</b> | <b>1025</b> | <b>1049</b> | <b>1063</b> | <b>1043</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>205</b> | <b>205</b> | <b>216</b> | <b>214</b> | <b>216</b> | <b>215</b> | <b>217</b> | <b>211</b> | <b>202</b>  | <b>194</b>  | <b>178</b>  | <b>173</b>  | <b>167</b>  | <b>152</b>  | <b>148</b>  | <b>142</b>  | <b>129</b>  |
| Smart Start 2020                             | 86         | 92         | 106        | 113        | 121        | 129        | 136        | 135        | 131         | 125         | 117         | 116         | 115         | 108         | 109         | 109         | 104         |
| Smart Start SS1-1000                         | 119        | 113        | 110        | 101        | 95         | 86         | 81         | 76         | 71          | 69          | 61          | 57          | 52          | 44          | 39          | 33          | 25          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>   | <b>0</b>   | <b>2</b>   | <b>8</b>   | <b>8</b>   | <b>8</b>   | <b>9</b>   | <b>9</b>   | <b>8</b>    | <b>13</b>   | <b>10</b>   | <b>19</b>   | <b>20</b>   | <b>21</b>   | <b>20</b>   | <b>22</b>   | <b>22</b>   |
| Intoxalock 1001A                             | 0          | 0          | 1          | 4          | 4          | 4          | 4          | 4          | 3           | 4           | 2           | 2           | 2           | 1           | 1           | 2           | 2           |
| Intoxalock 1001A Advanced                    | 0          | 0          | 1          | 4          | 4          | 4          | 5          | 5          | 5           | 9           | 8           | 17          | 18          | 20          | 19          | 20          | 20          |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>280</b> | <b>285</b> | <b>275</b> | <b>268</b> | <b>263</b> | <b>249</b> | <b>242</b> | <b>229</b> | <b>231</b>  | <b>223</b>  | <b>208</b>  | <b>199</b>  | <b>176</b>  | <b>168</b>  | <b>157</b>  | <b>148</b>  | <b>139</b>  |
| Draeger XT                                   | 280        | 285        | 275        | 268        | 263        | 249        | 242        | 229        | 231         | 223         | 208         | 199         | 176         | 168         | 157         | 148         | 139         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>56</b>  | <b>66</b>  | <b>99</b>  | <b>126</b> | <b>164</b> | <b>193</b> | <b>233</b> | <b>288</b> | <b>331</b>  | <b>348</b>  | <b>389</b>  | <b>422</b>  | <b>448</b>  | <b>484</b>  | <b>519</b>  | <b>548</b>  | <b>562</b>  |
| Interceptor M-1                              | 56         | 66         | 99         | 126        | 164        | 193        | 233        | 288        | 331         | 348         | 389         | 422         | 448         | 484         | 519         | 548         | 562         |
| <b>National Interlock Service LTD</b>        | <b>234</b> | <b>230</b> | <b>225</b> | <b>224</b> | <b>218</b> | <b>224</b> | <b>234</b> | <b>223</b> | <b>238</b>  | <b>231</b>  | <b>241</b>  | <b>212</b>  | <b>202</b>  | <b>196</b>  | <b>202</b>  | <b>201</b>  | <b>190</b>  |
| LifeSafer FC100 camera                       | 1          | 1          | 2          | 6          | 11         | 22         | 40         | 44         | 62          | 65          | 85          | 71          | 73          | 69          | 76          | 78          | 86          |
| LifeSafer FC100 no camera                    | 233        | 229        | 223        | 218        | 207        | 202        | 194        | 179        | 176         | 166         | 156         | 141         | 129         | 127         | 126         | 123         | 104         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |            | <b>4</b>   | <b>4</b>   | <b>4</b>   | <b>4</b>   | <b>4</b>   | <b>5</b>   | <b>5</b>   | <b>4</b>    | <b>4</b>    | <b>4</b>    | <b>3</b>    | <b>3</b>    | <b>4</b>    | <b>3</b>    | <b>2</b>    | <b>1</b>    |
| Best Labs FR9000                             |            | 4          | 4          | 4          | 4          | 4          | 5          | 5          | 4           | 4           | 4           | 3           | 3           | 4           | 3           | 2           | 1           |
| <b>Statewide Interlock Systemes, Inc.</b>    |            |            |            |            |            |            |            |            |             |             |             | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    |
| Alcohol Detection Systems DM-904             |            |            |            |            |            |            |            |            |             |             |             | 0           | 0           | 0           | 0           | 0           | 0           |

|  |          |          |           |           |           |           |           |           |           |            |            |            |            |            |            |            |            |
|--|----------|----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|------------|------------|------------|------------|------------|------------|------------|------------|
| <b>New York</b>                              | <b>3</b> | <b>6</b> | <b>18</b> | <b>26</b> | <b>36</b> | <b>46</b> | <b>61</b> | <b>80</b> | <b>89</b> | <b>116</b> | <b>128</b> | <b>136</b> | <b>144</b> | <b>140</b> | <b>131</b> | <b>140</b> | <b>125</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>2</b> | <b>12</b> | <b>19</b> | <b>25</b> | <b>35</b> | <b>45</b> | <b>62</b> | <b>68</b> | <b>82</b>  | <b>88</b>  | <b>93</b>  | <b>98</b>  | <b>95</b>  | <b>89</b>  | <b>89</b>  | <b>74</b>  |
| Smart Start 2020                             | 0        | 2        | 12        | 19        | 25        | 35        | 45        | 62        | 68        | 82         | 88         | 93         | 98         | 95         | 89         | 89         | 74         |
| Smart Start SS1-1000                         | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>0</b> | <b>2</b>  | <b>3</b>  | <b>6</b>  | <b>7</b>  | <b>12</b> | <b>13</b> | <b>15</b> | <b>19</b>  | <b>18</b>  | <b>19</b>  | <b>19</b>  | <b>20</b>  | <b>20</b>  | <b>22</b>  | <b>19</b>  |
| Intoxalock 1001A                             | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| Intoxalock 1001A Advanced                    | 0        | 0        | 2         | 3         | 6         | 7         | 12        | 13        | 15        | 18         | 18         | 19         | 19         | 20         | 20         | 22         | 19         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>2</b> | <b>3</b> | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>2</b>  | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>   | <b>3</b>   | <b>3</b>   | <b>3</b>   | <b>3</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   |
| Draeger XT                                   | 2        | 3        | 3         | 3         | 3         | 2         | 2         | 3         | 3         | 3          | 3          | 3          | 3          | 3          | 2          | 2          | 2          |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   |
| Interceptor M-1                              | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          |
| <b>National Interlock Service LTD</b>        | <b>1</b> | <b>1</b> | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>11</b>  | <b>18</b>  | <b>20</b>  | <b>23</b>  | <b>21</b>  | <b>19</b>  | <b>26</b>  | <b>29</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0         | 0         | 1         | 1         | 1         | 1         | 1         | 11         | 18         | 20         | 23         | 21         | 18         | 25         | 27         |
| LifeSafer FC100 no camera                    | 1        | 1        | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 0          | 0          | 0          | 0          | 0          | 1          | 1          | 2          |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Best Labs FR9000                             |          | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |           |           |           |           |           |           |           |            |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Alcohol Detection Systems DM-904             |          |          |           |           |           |           |           |           |           |            |            | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Niagara</b>                               | <b>3</b> | <b>6</b> | <b>10</b> | <b>24</b> | <b>36</b> | <b>44</b> | <b>52</b> | <b>59</b> | <b>63</b> | <b>70</b>  | <b>72</b>  | <b>78</b>  | <b>84</b>  | <b>91</b>  | <b>89</b>  | <b>90</b>  | <b>89</b>  |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>0</b> | <b>1</b>  | <b>3</b>  | <b>5</b>  | <b>7</b>  | <b>9</b>  | <b>11</b> | <b>12</b> | <b>11</b>  | <b>9</b>   | <b>11</b>  | <b>13</b>  | <b>11</b>  | <b>12</b>  | <b>12</b>  | <b>11</b>  |
| Smart Start 2020                             | 0        | 0        | 1         | 3         | 5         | 7         | 9         | 11        | 12        | 11         | 9          | 11         | 13         | 11         | 12         | 12         | 11         |
| Smart Start SS1-1000                         | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>1</b> | <b>2</b>  | <b>10</b> | <b>16</b> | <b>18</b> | <b>20</b> | <b>21</b> | <b>25</b> | <b>29</b>  | <b>34</b>  | <b>37</b>  | <b>39</b>  | <b>40</b>  | <b>40</b>  | <b>37</b>  | <b>35</b>  |
| Intoxalock 1001A                             | 0        | 1        | 2         | 10        | 16        | 18        | 20        | 21        | 25        | 29         | 34         | 37         | 39         | 40         | 40         | 37         | 35         |
| Intoxalock 1001A Advanced                    | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>3</b> | <b>5</b> | <b>7</b>  | <b>10</b> | <b>14</b> | <b>18</b> | <b>22</b> | <b>26</b> | <b>25</b> | <b>28</b>  | <b>27</b>  | <b>28</b>  | <b>30</b>  | <b>38</b>  | <b>35</b>  | <b>38</b>  | <b>41</b>  |
| Draeger XT                                   | 3        | 5        | 7         | 10        | 14        | 18        | 22        | 26        | 25        | 28         | 27         | 28         | 30         | 38         | 35         | 38         | 41         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Interceptor M-1                              | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| LifeSafer FC100 camera                       | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| LifeSafer FC100 no camera                    | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b> | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>1</b>   |
| Best Labs FR9000                             |          | 0        | 0         | 1         | 1         | 1         | 1         | 1         | 1         | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 1          |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |           |           |           |           |           |           |           |            |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>1</b>   | <b>1</b>   |
| Alcohol Detection Systems DM-904             |          |          |           |           |           |           |           |           |           |            |            | 0          | 0          | 0          | 0          | 1          | 1          |



|  |           |           |           |           |           |           |           |           |            |            |            |            |            |            |            |            |            |
|--|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|------------|------------|------------|------------|------------|------------|------------|------------|------------|
| <b>Oneida</b>                                | <b>23</b> | <b>26</b> | <b>37</b> | <b>51</b> | <b>70</b> | <b>79</b> | <b>84</b> | <b>93</b> | <b>101</b> | <b>106</b> | <b>107</b> | <b>110</b> | <b>115</b> | <b>115</b> | <b>112</b> | <b>110</b> | <b>100</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>  | <b>0</b>  | <b>2</b>  | <b>4</b>  | <b>7</b>  | <b>8</b>  | <b>9</b>  | <b>8</b>  | <b>10</b>  | <b>14</b>  | <b>16</b>  | <b>19</b>  | <b>20</b>  | <b>20</b>  | <b>21</b>  | <b>21</b>  | <b>14</b>  |
| Smart Start 2020                             | 0         | 0         | 2         | 4         | 7         | 8         | 9         | 8         | 10         | 14         | 16         | 19         | 20         | 20         | 21         | 21         | 14         |
| Smart Start SS1-1000                         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>2</b>  | <b>9</b>  | <b>17</b> | <b>25</b> | <b>34</b> | <b>40</b> | <b>46</b> | <b>52</b>  | <b>48</b>  | <b>43</b>  | <b>42</b>  | <b>42</b>  | <b>39</b>  | <b>32</b>  | <b>30</b>  | <b>26</b>  |
| Intoxalock 1001A                             | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 1          | 1          | 1          | 1          | 1          | 1          |
| Intoxalock 1001A Advanced                    | 0         | 2         | 9         | 17        | 25        | 34        | 40        | 46        | 52         | 48         | 43         | 41         | 41         | 38         | 31         | 29         | 25         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>1</b>   | <b>2</b>   | <b>3</b>   | <b>6</b>   | <b>8</b>   | <b>11</b>  | <b>13</b>  | <b>12</b>  | <b>11</b>  |
| Draeger XT                                   | 0         | 0         | 1         | 1         | 2         | 2         | 2         | 2         | 1          | 2          | 3          | 6          | 8          | 11         | 13         | 12         | 11         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>22</b> | <b>23</b> | <b>24</b> | <b>28</b> | <b>33</b> | <b>33</b> | <b>31</b> | <b>35</b> | <b>36</b>  | <b>40</b>  | <b>43</b>  | <b>42</b>  | <b>44</b>  | <b>44</b>  | <b>45</b>  | <b>46</b>  | <b>48</b>  |
| Interceptor M-1                              | 22        | 23        | 24        | 28        | 33        | 33        | 31        | 35        | 36         | 40         | 43         | 42         | 44         | 44         | 45         | 46         | 48         |
| <b>National Interlock Service LTD</b>        | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>3</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   |
| LifeSafer FC100 camera                       | 0         | 0         | 0         | 0         | 2         | 2         | 2         | 2         | 2          | 2          | 2          | 1          | 1          | 1          | 1          | 1          | 1          |
| LifeSafer FC100 no camera                    | 1         | 1         | 1         | 1         | 1         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Best Labs FR9000                             |           | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |           |           |           |           |           |           |           |            |            |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Alcohol Detection Systems DM-904             |           |           |           |           |           |           |           |           |            |            |            | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Onondaga</b>                              | <b>20</b> | <b>28</b> | <b>32</b> | <b>44</b> | <b>50</b> | <b>52</b> | <b>59</b> | <b>57</b> | <b>61</b>  | <b>93</b>  | <b>92</b>  | <b>103</b> | <b>115</b> | <b>136</b> | <b>122</b> | <b>128</b> | <b>122</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>4</b>  | <b>6</b>  | <b>6</b>   | <b>10</b>  | <b>10</b>  | <b>11</b>  | <b>14</b>  | <b>16</b>  | <b>19</b>  | <b>19</b>  | <b>14</b>  |
| Smart Start 2020                             | 0         | 0         | 0         | 1         | 1         | 2         | 4         | 6         | 6          | 10         | 10         | 11         | 14         | 16         | 19         | 19         | 14         |
| Smart Start SS1-1000                         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>   | <b>2</b>   | <b>3</b>   | <b>3</b>   | <b>3</b>   | <b>5</b>   | <b>7</b>   | <b>8</b>   | <b>7</b>   |
| Intoxalock 1001A                             | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 1          | 3          | 5          | 5          |
| Intoxalock 1001A Advanced                    | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 2          | 2          | 3          | 3          | 3          | 4          | 4          | 3          | 2          |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>3</b>   | <b>5</b>   | <b>5</b>   | <b>4</b>   | <b>4</b>   | <b>4</b>   | <b>5</b>   | <b>6</b>   | <b>7</b>   |
| Draeger XT                                   | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 3          | 5          | 5          | 4          | 4          | 4          | 5          | 6          | 7          |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>5</b>  | <b>5</b>  | <b>5</b>  | <b>6</b>  | <b>8</b>  | <b>8</b>  | <b>7</b>  | <b>8</b>  | <b>12</b>  | <b>13</b>  | <b>13</b>  | <b>12</b>  | <b>12</b>  | <b>9</b>   | <b>9</b>   | <b>9</b>   | <b>9</b>   |
| Interceptor M-1                              | 5         | 5         | 5         | 6         | 8         | 8         | 7         | 8         | 12         | 13         | 13         | 12         | 12         | 9          | 9          | 9          | 9          |
| <b>National Interlock Service LTD</b>        | <b>14</b> | <b>22</b> | <b>26</b> | <b>36</b> | <b>39</b> | <b>40</b> | <b>46</b> | <b>41</b> | <b>38</b>  | <b>63</b>  | <b>61</b>  | <b>73</b>  | <b>82</b>  | <b>102</b> | <b>82</b>  | <b>86</b>  | <b>85</b>  |
| LifeSafer FC100 camera                       | 0         | 0         | 0         | 2         | 4         | 4         | 5         | 5         | 5          | 6          | 5          | 4          | 8          | 8          | 8          | 8          | 8          |
| LifeSafer FC100 no camera                    | 14        | 22        | 26        | 34        | 35        | 36        | 41        | 36        | 33         | 57         | 56         | 69         | 74         | 94         | 74         | 78         | 77         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Best Labs FR9000                             |           | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |           |           |           |           |           |           |           |            |            |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Alcohol Detection Systems DM-904             |           |           |           |           |           |           |           |           |            |            |            | 0          | 0          | 0          | 0          | 0          | 0          |

|  |           |           |           |           |           |           |           |            |            |            |            |            |            |            |            |            |            |
|--|-----------|-----------|-----------|-----------|-----------|-----------|-----------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|
| <b>Ontario</b>                               | <b>6</b>  | <b>9</b>  | <b>15</b> | <b>18</b> | <b>31</b> | <b>37</b> | <b>46</b> | <b>52</b>  | <b>62</b>  | <b>80</b>  | <b>82</b>  | <b>99</b>  | <b>99</b>  | <b>108</b> | <b>110</b> | <b>116</b> | <b>107</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>3</b>  | <b>7</b>  | <b>10</b> | <b>13</b>  | <b>14</b>  | <b>19</b>  | <b>19</b>  | <b>22</b>  | <b>21</b>  | <b>24</b>  | <b>24</b>  | <b>24</b>  | <b>25</b>  |
| Smart Start 2020                             | 0         | 0         | 0         | 0         | 3         | 7         | 10        | 13         | 14         | 19         | 19         | 22         | 21         | 24         | 24         | 24         | 25         |
| Smart Start SS1-1000                         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>1</b>  | <b>6</b>  | <b>7</b>  | <b>15</b> | <b>16</b> | <b>19</b> | <b>22</b>  | <b>27</b>  | <b>36</b>  | <b>40</b>  | <b>52</b>  | <b>55</b>  | <b>59</b>  | <b>66</b>  | <b>70</b>  | <b>67</b>  |
| Intoxalock 1001A                             | 0         | 0         | 3         | 3         | 8         | 9         | 11        | 12         | 15         | 23         | 25         | 34         | 36         | 39         | 46         | 42         | 37         |
| Intoxalock 1001A Advanced                    | 0         | 1         | 3         | 4         | 7         | 7         | 8         | 10         | 12         | 13         | 15         | 18         | 19         | 20         | 20         | 28         | 30         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Draeger XT                                   | 1         | 1         | 1         | 1         | 1         | 2         | 2         | 2          | 2          | 2          | 2          | 2          | 0          | 0          | 0          | 0          | 0          |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>5</b>  | <b>4</b>  | <b>5</b>  | <b>6</b>  | <b>5</b>  | <b>5</b>  | <b>6</b>  | <b>6</b>   | <b>6</b>   | <b>4</b>   | <b>4</b>   | <b>4</b>   | <b>4</b>   | <b>4</b>   | <b>5</b>   | <b>5</b>   | <b>5</b>   |
| Interceptor M-1                              | 5         | 4         | 5         | 6         | 5         | 5         | 6         | 6          | 6          | 4          | 4          | 4          | 4          | 4          | 5          | 5          | 5          |
| <b>National Interlock Service LTD</b>        | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>   | <b>1</b>   | <b>5</b>   | <b>4</b>   | <b>8</b>   | <b>8</b>   | <b>10</b>  | <b>8</b>   | <b>11</b>  | <b>7</b>   |
| LifeSafer FC100 camera                       | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 1          | 0          | 0          | 2          | 2          | 4          | 3          | 6          | 5          |
| LifeSafer FC100 no camera                    | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 5          | 4          | 6          | 6          | 6          | 5          | 5          | 2          |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>3</b>  | <b>3</b>  | <b>4</b>  | <b>7</b>  | <b>7</b>  | <b>9</b>  | <b>9</b>   | <b>12</b>  | <b>14</b>  | <b>13</b>  | <b>11</b>  | <b>11</b>  | <b>11</b>  | <b>7</b>   | <b>6</b>   | <b>3</b>   |
| Best Labs FR9000                             |           | 3         | 3         | 4         | 7         | 7         | 9         | 9          | 12         | 14         | 13         | 11         | 11         | 11         | 7          | 6          | 3          |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |           |           |           |           |           |           |            |            |            |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Alcohol Detection Systems DM-904             |           |           |           |           |           |           |           |            |            |            |            | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Orange</b>                                | <b>15</b> | <b>20</b> | <b>26</b> | <b>42</b> | <b>66</b> | <b>75</b> | <b>94</b> | <b>108</b> | <b>125</b> | <b>156</b> | <b>168</b> | <b>181</b> | <b>188</b> | <b>195</b> | <b>209</b> | <b>228</b> | <b>210</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>1</b>  | <b>4</b>  | <b>5</b>  | <b>7</b>  | <b>16</b> | <b>18</b> | <b>23</b> | <b>30</b>  | <b>35</b>  | <b>38</b>  | <b>38</b>  | <b>40</b>  | <b>40</b>  | <b>38</b>  | <b>36</b>  | <b>36</b>  | <b>44</b>  |
| Smart Start 2020                             | 1         | 4         | 5         | 7         | 16        | 18        | 23        | 30         | 35         | 38         | 38         | 40         | 40         | 38         | 36         | 36         | 44         |
| Smart Start SS1-1000                         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>3</b>  | <b>8</b>  | <b>19</b> | <b>21</b> | <b>27</b> | <b>31</b>  | <b>41</b>  | <b>51</b>  | <b>52</b>  | <b>58</b>  | <b>60</b>  | <b>63</b>  | <b>67</b>  | <b>76</b>  | <b>68</b>  |
| Intoxalock 1001A                             | 0         | 0         | 0         | 4         | 10        | 11        | 14        | 15         | 23         | 28         | 26         | 21         | 22         | 18         | 20         | 20         | 17         |
| Intoxalock 1001A Advanced                    | 0         | 0         | 3         | 4         | 9         | 10        | 13        | 16         | 18         | 23         | 26         | 37         | 38         | 45         | 47         | 56         | 51         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>3</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   |
| Draeger XT                                   | 3         | 2         | 2         | 2         | 2         | 2         | 2         | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 2          |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>10</b> | <b>11</b> | <b>12</b> | <b>12</b> | <b>12</b> | <b>12</b> | <b>13</b> | <b>15</b>  | <b>16</b>  | <b>17</b>  | <b>18</b>  | <b>18</b>  | <b>19</b>  | <b>20</b>  | <b>21</b>  | <b>22</b>  | <b>25</b>  |
| Interceptor M-1                              | 10        | 11        | 12        | 12        | 12        | 12        | 13        | 15         | 16         | 17         | 18         | 18         | 19         | 20         | 21         | 22         | 25         |
| <b>National Interlock Service LTD</b>        | <b>1</b>  | <b>3</b>  | <b>4</b>  | <b>13</b> | <b>17</b> | <b>22</b> | <b>28</b> | <b>29</b>  | <b>29</b>  | <b>45</b>  | <b>54</b>  | <b>56</b>  | <b>60</b>  | <b>65</b>  | <b>77</b>  | <b>86</b>  | <b>65</b>  |
| LifeSafer FC100 camera                       | 1         | 2         | 2         | 5         | 8         | 11        | 15        | 16         | 16         | 31         | 43         | 39         | 43         | 47         | 54         | 61         | 47         |
| LifeSafer FC100 no camera                    | 0         | 1         | 2         | 8         | 9         | 11        | 13        | 13         | 13         | 14         | 11         | 17         | 17         | 18         | 23         | 25         | 18         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>   | <b>2</b>   | <b>3</b>   | <b>4</b>   | <b>7</b>   | <b>6</b>   | <b>6</b>   | <b>5</b>   | <b>5</b>   | <b>5</b>   |
| Best Labs FR9000                             |           | 0         | 0         | 0         | 0         | 0         | 1         | 1          | 2          | 3          | 4          | 7          | 6          | 6          | 5          | 5          | 5          |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |           |           |           |           |           |           |            |            |            |            | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   |
| Alcohol Detection Systems DM-904             |           |           |           |           |           |           |           |            |            |            |            | 0          | 1          | 1          | 1          | 1          | 1          |

|  |          |          |          |           |           |           |           |           |           |           |           |           |           |           |           |           |           |
|--|----------|----------|----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| <b>Orleans</b>                               | <b>1</b> | <b>2</b> | <b>5</b> | <b>8</b>  | <b>9</b>  | <b>10</b> | <b>10</b> | <b>11</b> | <b>10</b> | <b>12</b> | <b>15</b> | <b>19</b> | <b>18</b> | <b>21</b> | <b>20</b> | <b>22</b> | <b>19</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>1</b> | <b>4</b> | <b>5</b>  | <b>6</b>  | <b>6</b>  | <b>6</b>  | <b>7</b>  | <b>6</b>  | <b>6</b>  | <b>9</b>  | <b>12</b> | <b>12</b> | <b>13</b> | <b>13</b> | <b>13</b> | <b>11</b> |
| Smart Start 2020                             | 0        | 1        | 4        | 5         | 6         | 6         | 6         | 7         | 6         | 6         | 9         | 12        | 12        | 13        | 13        | 13        | 11        |
| Smart Start SS1-1000                         | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>5</b>  | <b>5</b>  |
| Intoxalock 1001A                             | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0        | 0        | 0        | 0         | 0         | 1         | 1         | 1         | 1         | 1         | 1         | 2         | 2         | 3         | 3         | 5         | 5         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  |
| Interceptor M-1                              | 1        | 1        | 1        | 2         | 2         | 2         | 2         | 2         | 2         | 2         | 2         | 2         | 2         | 2         | 2         | 2         | 2         |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>0</b> | <b>0</b> | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>2</b>  | <b>3</b>  | <b>2</b>  | <b>2</b>  | <b>1</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0        | 1         | 1         | 1         | 1         | 1         | 1         | 2         | 2         | 2         | 1         | 1         | 1         | 1         | 1         |
| LifeSafer FC100 no camera                    | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 2         | 1         | 1         | 0         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |          |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |          |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Oswego</b>                                | <b>5</b> | <b>6</b> | <b>9</b> | <b>14</b> | <b>21</b> | <b>25</b> | <b>27</b> | <b>27</b> | <b>27</b> | <b>27</b> | <b>27</b> | <b>26</b> | <b>25</b> | <b>26</b> | <b>29</b> | <b>32</b> | <b>32</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>0</b> | <b>1</b> | <b>2</b>  | <b>4</b>  | <b>5</b>  | <b>6</b>  | <b>6</b>  | <b>6</b>  | <b>4</b>  | <b>5</b>  | <b>3</b>  | <b>3</b>  | <b>4</b>  | <b>6</b>  | <b>6</b>  | <b>6</b>  |
| Smart Start 2020                             | 0        | 0        | 1        | 2         | 4         | 5         | 6         | 6         | 6         | 4         | 5         | 3         | 3         | 4         | 6         | 6         | 6         |
| Smart Start SS1-1000                         | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>0</b> | <b>1</b> | <b>3</b>  | <b>4</b>  | <b>6</b>  | <b>8</b>  | <b>8</b>  | <b>9</b>  | <b>11</b> | <b>12</b> | <b>13</b> | <b>13</b> | <b>14</b> | <b>15</b> | <b>16</b> | <b>17</b> |
| Intoxalock 1001A                             | 0        | 0        | 0        | 1         | 2         | 2         | 3         | 3         | 5         | 5         | 6         | 5         | 5         | 4         | 3         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0        | 0        | 1        | 2         | 2         | 4         | 5         | 5         | 4         | 6         | 6         | 8         | 8         | 10        | 12        | 16        | 17        |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Interceptor M-1                              | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>National Interlock Service LTD</b>        | <b>5</b> | <b>4</b> | <b>4</b> | <b>6</b>  | <b>9</b>  | <b>9</b>  | <b>10</b> | <b>9</b>  | <b>8</b>  | <b>7</b>  | <b>7</b>  | <b>7</b>  | <b>6</b>  | <b>5</b>  | <b>5</b>  | <b>9</b>  | <b>8</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0        | 0         | 1         | 1         | 2         | 2         | 2         | 2         | 2         | 4         | 4         | 4         | 3         | 7         | 8         |
| LifeSafer FC100 no camera                    | 5        | 4        | 4        | 6         | 8         | 8         | 8         | 7         | 6         | 5         | 5         | 3         | 2         | 1         | 2         | 2         | 0         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>2</b> | <b>3</b> | <b>3</b>  | <b>4</b>  | <b>5</b>  | <b>3</b>  | <b>4</b>  | <b>4</b>  | <b>5</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>1</b>  | <b>1</b>  |
| Best Labs FR9000                             |          | 2        | 3        | 3         | 4         | 5         | 3         | 4         | 4         | 5         | 3         | 3         | 3         | 3         | 3         | 1         | 1         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |          |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |          |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |

|  |           |           |           |           |           |           |           |           |           |           |           |           |           |           |           |           |           |
|--|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| <b>Otsego</b>                                | <b>12</b> | <b>14</b> | <b>14</b> | <b>17</b> | <b>21</b> | <b>23</b> | <b>27</b> | <b>31</b> | <b>33</b> | <b>39</b> | <b>39</b> | <b>37</b> | <b>38</b> | <b>38</b> | <b>42</b> | <b>38</b> | <b>42</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>3</b>  | <b>4</b>  | <b>4</b>  | <b>5</b>  | <b>6</b>  | <b>6</b>  | <b>5</b>  | <b>3</b>  | <b>3</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>5</b>  |
| Smart Start 2020                             | 0         | 1         | 1         | 1         | 3         | 4         | 4         | 5         | 6         | 6         | 5         | 3         | 3         | 2         | 2         | 2         | 5         |
| Smart Start SS1-1000                         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>3</b>  | <b>5</b>  | <b>7</b>  | <b>9</b>  | <b>11</b> | <b>12</b> | <b>13</b> | <b>14</b> | <b>16</b> | <b>17</b> | <b>18</b> | <b>22</b> | <b>21</b> | <b>22</b> |
| Intoxalock 1001A                             | 0         | 0         | 0         | 2         | 4         | 5         | 6         | 6         | 7         | 8         | 8         | 9         | 10        | 12        | 16        | 16        | 16        |
| Intoxalock 1001A Advanced                    | 0         | 1         | 1         | 1         | 1         | 2         | 3         | 5         | 5         | 5         | 6         | 7         | 7         | 6         | 6         | 5         | 6         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>12</b> | <b>12</b> | <b>12</b> | <b>12</b> | <b>12</b> | <b>10</b> | <b>13</b> | <b>14</b> | <b>14</b> | <b>14</b> | <b>15</b> | <b>14</b> | <b>14</b> | <b>14</b> | <b>14</b> | <b>14</b> | <b>14</b> |
| Interceptor M-1                              | 12        | 12        | 12        | 12        | 12        | 10        | 13        | 14        | 14        | 14        | 15        | 14        | 14        | 14        | 14        | 14        | 14        |
| <b>National Interlock Service LTD</b>        | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>4</b>  | <b>5</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>2</b>  | <b>0</b>  | <b>0</b>  |
| LifeSafer FC100 camera                       | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 2         | 3         | 2         | 2         | 2         | 2         | 0         | 0         |
| LifeSafer FC100 no camera                    | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 2         | 2         | 1         | 1         | 1         | 0         | 0         | 0         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  |
| Best Labs FR9000                             |           | 0         | 0         | 1         | 1         | 2         | 1         | 1         | 1         | 2         | 0         | 0         | 0         | 0         | 1         | 1         | 1         |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |           |           |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |           |           |           |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Putnam</b>                                | <b>32</b> | <b>38</b> | <b>39</b> | <b>45</b> | <b>46</b> | <b>53</b> | <b>55</b> | <b>55</b> | <b>61</b> | <b>63</b> | <b>67</b> | <b>69</b> | <b>76</b> | <b>75</b> | <b>81</b> | <b>88</b> | <b>84</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>3</b>  | <b>2</b>  | <b>3</b>  | <b>4</b>  | <b>5</b>  | <b>6</b>  | <b>10</b> | <b>11</b> | <b>12</b> | <b>16</b> | <b>15</b> | <b>15</b> | <b>15</b> | <b>14</b> |
| Smart Start 2020                             | 0         | 1         | 1         | 3         | 2         | 3         | 4         | 5         | 6         | 10        | 11        | 11        | 15        | 15        | 15        | 15        | 14        |
| Smart Start SS1-1000                         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>3</b>  | <b>4</b>  | <b>6</b>  | <b>8</b>  | <b>12</b> | <b>13</b> | <b>13</b> | <b>16</b> | <b>18</b> | <b>22</b> | <b>24</b> | <b>25</b> | <b>26</b> | <b>28</b> | <b>35</b> | <b>34</b> |
| Intoxalock 1001A                             | 0         | 2         | 3         | 3         | 3         | 6         | 7         | 7         | 7         | 8         | 10        | 11        | 11        | 11        | 11        | 15        | 15        |
| Intoxalock 1001A Advanced                    | 0         | 1         | 1         | 3         | 5         | 6         | 6         | 6         | 9         | 10        | 12        | 13        | 14        | 15        | 17        | 20        | 19        |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>2</b>  | <b>2</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>2</b>  |
| Draeger XT                                   | 2         | 2         | 1         | 1         | 1         | 1         | 1         | 1         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 2         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>26</b> | <b>26</b> | <b>26</b> | <b>26</b> | <b>25</b> | <b>26</b> | <b>26</b> | <b>26</b> | <b>27</b> | <b>23</b> | <b>22</b> | <b>22</b> | <b>23</b> | <b>23</b> | <b>23</b> | <b>23</b> | <b>23</b> |
| Interceptor M-1                              | 26        | 26        | 26        | 26        | 25        | 26        | 26        | 26        | 27        | 23        | 22        | 22        | 23        | 23        | 23        | 23        | 23        |
| <b>National Interlock Service LTD</b>        | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>6</b>  | <b>7</b>  | <b>7</b>  | <b>7</b>  | <b>6</b>  | <b>7</b>  | <b>4</b>  | <b>5</b>  | <b>5</b>  | <b>5</b>  | <b>4</b>  | <b>7</b>  | <b>7</b>  | <b>4</b>  |
| LifeSafer FC100 camera                       | 0         | 0         | 0         | 1         | 1         | 2         | 2         | 2         | 2         | 2         | 3         | 3         | 3         | 4         | 5         | 5         | 3         |
| LifeSafer FC100 no camera                    | 4         | 4         | 4         | 5         | 6         | 5         | 5         | 4         | 5         | 2         | 2         | 2         | 2         | 0         | 2         | 2         | 1         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>5</b>  | <b>8</b>  | <b>7</b>  | <b>6</b>  | <b>6</b>  | <b>6</b>  | <b>7</b>  | <b>6</b>  | <b>6</b>  |
| Best Labs FR9000                             |           | 2         | 3         | 3         | 3         | 4         | 4         | 4         | 5         | 8         | 7         | 6         | 6         | 6         | 7         | 6         | 6         |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |           |           |           |           |           |           |           |           |           |           | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  |
| Alcohol Detection Systems DM-904             |           |           |           |           |           |           |           |           |           |           |           | 0         | 1         | 1         | 1         | 1         | 1         |

|  |           |           |           |           |           |           |           |            |            |            |            |            |            |            |            |            |            |
|--|-----------|-----------|-----------|-----------|-----------|-----------|-----------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|
| <b>Queens</b>                                | <b>13</b> | <b>24</b> | <b>32</b> | <b>41</b> | <b>59</b> | <b>70</b> | <b>84</b> | <b>100</b> | <b>115</b> | <b>137</b> | <b>147</b> | <b>157</b> | <b>180</b> | <b>179</b> | <b>195</b> | <b>202</b> | <b>222</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>6</b>  | <b>7</b>  | <b>8</b>  | <b>14</b> | <b>21</b> | <b>23</b> | <b>32</b> | <b>46</b>  | <b>57</b>  | <b>67</b>  | <b>65</b>  | <b>76</b>  | <b>87</b>  | <b>84</b>  | <b>90</b>  | <b>90</b>  | <b>104</b> |
| Smart Start 2020                             | 2         | 4         | 5         | 11        | 19        | 21        | 30        | 45         | 55         | 65         | 63         | 74         | 86         | 83         | 89         | 89         | 104        |
| Smart Start SS1-1000                         | 4         | 3         | 3         | 3         | 2         | 2         | 2         | 1          | 2          | 2          | 2          | 2          | 1          | 1          | 1          | 1          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>1</b>  | <b>3</b>  | <b>4</b>  | <b>10</b> | <b>17</b> | <b>20</b> | <b>21</b>  | <b>24</b>  | <b>29</b>  | <b>36</b>  | <b>36</b>  | <b>39</b>  | <b>39</b>  | <b>38</b>  | <b>38</b>  | <b>39</b>  |
| Intoxalock 1001A                             | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| Intoxalock 1001A Advanced                    | 0         | 1         | 3         | 4         | 10        | 17        | 20        | 21         | 24         | 29         | 36         | 36         | 39         | 39         | 38         | 38         | 39         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>3</b>  | <b>3</b>  | <b>5</b>  | <b>5</b>  | <b>7</b>  | <b>9</b>  | <b>9</b>  | <b>9</b>   | <b>8</b>   | <b>8</b>   | <b>8</b>   | <b>7</b>   | <b>7</b>   | <b>7</b>   | <b>8</b>   | <b>8</b>   | <b>8</b>   |
| Draeger XT                                   | 3         | 3         | 5         | 5         | 7         | 9         | 9         | 9          | 8          | 8          | 8          | 7          | 7          | 7          | 8          | 8          | 8          |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>3</b>   | <b>5</b>   | <b>5</b>   | <b>7</b>   | <b>9</b>   | <b>10</b>  | <b>11</b>  | <b>12</b>  | <b>13</b>  | <b>14</b>  |
| Interceptor M-1                              | 0         | 1         | 1         | 1         | 1         | 1         | 2         | 3          | 5          | 5          | 7          | 9          | 10         | 11         | 12         | 13         | 14         |
| <b>National Interlock Service LTD</b>        | <b>4</b>  | <b>4</b>  | <b>6</b>  | <b>8</b>  | <b>11</b> | <b>11</b> | <b>10</b> | <b>11</b>  | <b>11</b>  | <b>18</b>  | <b>21</b>  | <b>18</b>  | <b>26</b>  | <b>26</b>  | <b>34</b>  | <b>42</b>  | <b>46</b>  |
| LifeSafer FC100 camera                       | 0         | 0         | 1         | 3         | 6         | 6         | 6         | 7          | 7          | 15         | 19         | 16         | 22         | 22         | 30         | 38         | 43         |
| LifeSafer FC100 no camera                    | 4         | 4         | 5         | 5         | 5         | 5         | 4         | 4          | 4          | 3          | 2          | 2          | 4          | 4          | 4          | 4          | 3          |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>8</b>  | <b>9</b>  | <b>9</b>  | <b>9</b>  | <b>9</b>  | <b>11</b> | <b>10</b>  | <b>10</b>  | <b>10</b>  | <b>10</b>  | <b>11</b>  | <b>11</b>  | <b>12</b>  | <b>13</b>  | <b>11</b>  | <b>11</b>  |
| Best Labs FR9000                             |           | 8         | 9         | 9         | 9         | 9         | 11        | 10         | 10         | 10         | 10         | 11         | 11         | 12         | 13         | 11         | 11         |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |           |           |           |           |           |           |            |            |            |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Alcohol Detection Systems DM-904             |           |           |           |           |           |           |           |            |            |            |            | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Rensselaer</b>                            | <b>3</b>  | <b>4</b>  | <b>9</b>  | <b>13</b> | <b>21</b> | <b>24</b> | <b>27</b> | <b>27</b>  | <b>39</b>  | <b>45</b>  | <b>60</b>  | <b>59</b>  | <b>69</b>  | <b>71</b>  | <b>70</b>  | <b>70</b>  | <b>66</b>  |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>  | <b>0</b>  | <b>2</b>  | <b>3</b>  | <b>7</b>  | <b>9</b>  | <b>11</b> | <b>11</b>  | <b>21</b>  | <b>25</b>  | <b>39</b>  | <b>42</b>  | <b>48</b>  | <b>50</b>  | <b>48</b>  | <b>48</b>  | <b>43</b>  |
| Smart Start 2020                             | 0         | 0         | 2         | 3         | 7         | 9         | 11        | 11         | 21         | 25         | 39         | 42         | 48         | 50         | 48         | 48         | 43         |
| Smart Start SS1-1000                         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>   | <b>3</b>   | <b>3</b>   | <b>4</b>   | <b>3</b>   | <b>3</b>   | <b>4</b>   | <b>3</b>   | <b>3</b>   | <b>3</b>   |
| Intoxalock 1001A                             | 0         | 0         | 0         | 0         | 1         | 1         | 2         | 2          | 3          | 3          | 3          | 2          | 2          | 2          | 2          | 2          | 2          |
| Intoxalock 1001A Advanced                    | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 1          | 1          | 1          | 2          | 1          | 1          | 1          |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>2</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   |
| Draeger XT                                   | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1          | 1          | 1          | 1          | 1          | 2          | 1          | 1          | 1          | 1          |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>4</b>  | <b>5</b>  | <b>6</b>  | <b>6</b>  | <b>6</b>   | <b>7</b>   | <b>6</b>   | <b>6</b>   | <b>6</b>   | <b>7</b>   | <b>7</b>   | <b>7</b>   | <b>8</b>   | <b>8</b>   |
| Interceptor M-1                              | 2         | 3         | 3         | 4         | 5         | 6         | 6         | 6          | 7          | 6          | 6          | 6          | 7          | 7          | 7          | 8          | 8          |
| <b>National Interlock Service LTD</b>        | <b>0</b>  | <b>0</b>  | <b>2</b>  | <b>4</b>  | <b>6</b>  | <b>6</b>  | <b>6</b>  | <b>6</b>   | <b>6</b>   | <b>8</b>   | <b>8</b>   | <b>5</b>   | <b>6</b>   | <b>6</b>   | <b>8</b>   | <b>8</b>   | <b>9</b>   |
| LifeSafer FC100 camera                       | 0         | 0         | 2         | 4         | 4         | 4         | 4         | 4          | 4          | 5          | 6          | 5          | 5          | 5          | 7          | 7          | 9          |
| LifeSafer FC100 no camera                    | 0         | 0         | 0         | 0         | 2         | 2         | 2         | 2          | 2          | 3          | 2          | 0          | 1          | 1          | 1          | 1          | 0          |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>   | <b>1</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>1</b>   | <b>0</b>   | <b>0</b>   |
| Best Labs FR9000                             |           | 0         | 1         | 1         | 1         | 1         | 1         | 1          | 1          | 2          | 2          | 2          | 2          | 2          | 1          | 0          | 0          |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |           |           |           |           |           |           |            |            |            |            | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   |
| Alcohol Detection Systems DM-904             |           |           |           |           |           |           |           |            |            |            |            | 0          | 1          | 1          | 2          | 2          | 2          |

|  |          |          |          |           |           |           |           |           |           |           |           |           |           |           |           |           |           |
|--|----------|----------|----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| <b>Richmond</b>                              | <b>0</b> | <b>2</b> | <b>4</b> | <b>8</b>  | <b>13</b> | <b>19</b> | <b>26</b> | <b>29</b> | <b>33</b> | <b>38</b> | <b>41</b> | <b>43</b> | <b>41</b> | <b>40</b> | <b>37</b> | <b>29</b> | <b>30</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>1</b>  | <b>3</b>  | <b>6</b>  | <b>9</b>  | <b>12</b> | <b>13</b> | <b>15</b> | <b>15</b> | <b>11</b> | <b>15</b> | <b>12</b> | <b>12</b> | <b>14</b> |
| Smart Start 2020                             | 0        | 0        | 0        | 0         | 1         | 3         | 6         | 9         | 12        | 13        | 15        | 15        | 11        | 15        | 12        | 12        | 14        |
| Smart Start SS1-1000                         | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>1</b> | <b>3</b> | <b>5</b>  | <b>8</b>  | <b>11</b> | <b>13</b> | <b>13</b> | <b>14</b> | <b>16</b> | <b>17</b> | <b>17</b> | <b>17</b> | <b>16</b> | <b>16</b> | <b>8</b>  | <b>7</b>  |
| Intoxalock 1001A                             | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0        | 1        | 3        | 5         | 8         | 11        | 13        | 13        | 14        | 16        | 17        | 17        | 17        | 16        | 16        | 8         | 7         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  |
| Interceptor M-1                              | 0        | 0        | 0        | 0         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>1</b> | <b>1</b> | <b>3</b>  | <b>3</b>  | <b>4</b>  | <b>6</b>  | <b>6</b>  | <b>6</b>  | <b>8</b>  | <b>8</b>  | <b>10</b> | <b>11</b> | <b>8</b>  | <b>8</b>  | <b>8</b>  | <b>8</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 1        | 3         | 3         | 4         | 6         | 6         | 6         | 8         | 8         | 10        | 11        | 8         | 8         | 8         | 8         |
| LifeSafer FC100 no camera                    | 0        | 1        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |          |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |          |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Rockland</b>                              | <b>7</b> | <b>8</b> | <b>8</b> | <b>17</b> | <b>21</b> | <b>22</b> | <b>32</b> | <b>35</b> | <b>41</b> | <b>45</b> | <b>49</b> | <b>55</b> | <b>61</b> | <b>65</b> | <b>58</b> | <b>57</b> | <b>65</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>2</b> | <b>2</b> | <b>2</b> | <b>8</b>  | <b>10</b> | <b>10</b> | <b>13</b> | <b>16</b> | <b>19</b> | <b>22</b> | <b>23</b> | <b>26</b> | <b>31</b> | <b>34</b> | <b>26</b> | <b>26</b> | <b>28</b> |
| Smart Start 2020                             | 1        | 1        | 1        | 7         | 9         | 9         | 12        | 15        | 18        | 21        | 22        | 25        | 30        | 33        | 25        | 25        | 27        |
| Smart Start SS1-1000                         | 1        | 1        | 1        | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>2</b>  | <b>4</b>  | <b>4</b>  | <b>6</b>  | <b>7</b>  | <b>9</b>  | <b>9</b>  | <b>12</b> | <b>11</b> | <b>13</b> | <b>15</b> | <b>16</b> | <b>12</b> | <b>13</b> |
| Intoxalock 1001A                             | 0        | 0        | 0        | 1         | 2         | 2         | 4         | 5         | 4         | 4         | 3         | 3         | 3         | 3         | 3         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0        | 0        | 0        | 1         | 2         | 2         | 2         | 2         | 5         | 5         | 9         | 8         | 10        | 12        | 13        | 12        | 13        |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>2</b> | <b>1</b> | <b>1</b> | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>4</b>  | <b>5</b>  | <b>5</b>  | <b>5</b>  | <b>5</b>  | <b>8</b>  |
| Interceptor M-1                              | 2        | 1        | 1        | 1         | 1         | 0         | 0         | 1         | 2         | 3         | 3         | 4         | 5         | 5         | 5         | 5         | 8         |
| <b>National Interlock Service LTD</b>        | <b>3</b> | <b>4</b> | <b>4</b> | <b>5</b>  | <b>5</b>  | <b>7</b>  | <b>12</b> | <b>9</b>  | <b>9</b>  | <b>10</b> | <b>10</b> | <b>13</b> | <b>11</b> | <b>10</b> | <b>11</b> | <b>14</b> | <b>16</b> |
| LifeSafer FC100 camera                       | 0        | 0        | 0        | 1         | 1         | 3         | 6         | 5         | 5         | 4         | 4         | 8         | 8         | 9         | 9         | 12        | 14        |
| LifeSafer FC100 no camera                    | 3        | 4        | 4        | 4         | 4         | 4         | 6         | 4         | 4         | 6         | 6         | 5         | 3         | 1         | 2         | 2         | 2         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>1</b> | <b>1</b> | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 1        | 1        | 1         | 1         | 1         | 1         | 2         | 2         | 1         | 1         | 1         | 1         | 1         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |          |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |          |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |

|  |           |           |           |           |            |            |            |            |            |            |            |            |            |            |            |            |            |
|--|-----------|-----------|-----------|-----------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|
| <b>Saratoga</b>                              | <b>68</b> | <b>73</b> | <b>85</b> | <b>96</b> | <b>105</b> | <b>111</b> | <b>125</b> | <b>127</b> | <b>133</b> | <b>148</b> | <b>157</b> | <b>167</b> | <b>177</b> | <b>177</b> | <b>180</b> | <b>182</b> | <b>163</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>  | <b>3</b>  | <b>10</b> | <b>11</b> | <b>12</b>  | <b>14</b>  | <b>14</b>  | <b>14</b>  | <b>12</b>  | <b>14</b>  | <b>18</b>  | <b>19</b>  | <b>27</b>  | <b>29</b>  | <b>30</b>  | <b>30</b>  | <b>9</b>   |
| Smart Start 2020                             | 0         | 3         | 10        | 11        | 12         | 14         | 14         | 14         | 12         | 14         | 18         | 19         | 27         | 29         | 30         | 30         | 9          |
| Smart Start SS1-1000                         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>2</b>  | <b>3</b>  | <b>3</b>   | <b>5</b>   | <b>6</b>   | <b>7</b>   | <b>11</b>  | <b>13</b>  | <b>11</b>  | <b>13</b>  | <b>14</b>  | <b>14</b>  | <b>16</b>  | <b>21</b>  | <b>26</b>  |
| Intoxalock 1001A                             | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          |
| Intoxalock 1001A Advanced                    | 0         | 0         | 2         | 3         | 3          | 5          | 6          | 7          | 10         | 12         | 10         | 12         | 13         | 13         | 15         | 20         | 25         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   |
| Draeger XT                                   | 0         | 1         | 1         | 1         | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>68</b> | <b>68</b> | <b>70</b> | <b>78</b> | <b>85</b>  | <b>87</b>  | <b>95</b>  | <b>95</b>  | <b>99</b>  | <b>102</b> | <b>103</b> | <b>110</b> | <b>114</b> | <b>114</b> | <b>116</b> | <b>114</b> | <b>108</b> |
| Interceptor M-1                              | 68        | 68        | 70        | 78        | 85         | 87         | 95         | 95         | 99         | 102        | 103        | 110        | 114        | 114        | 116        | 114        | 108        |
| <b>National Interlock Service LTD</b>        | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>2</b>  | <b>3</b>   | <b>3</b>   | <b>9</b>   | <b>10</b>  | <b>10</b>  | <b>18</b>  | <b>24</b>  | <b>24</b>  | <b>21</b>  | <b>18</b>  | <b>16</b>  | <b>15</b>  | <b>18</b>  |
| LifeSafer FC100 camera                       | 0         | 0         | 1         | 2         | 3          | 3          | 9          | 10         | 10         | 18         | 24         | 24         | 21         | 18         | 16         | 15         | 18         |
| LifeSafer FC100 no camera                    | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>   | <b>1</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Best Labs FR9000                             |           | 1         | 1         | 1         | 1          | 1          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |           |           |           |            |            |            |            |            |            |            | <b>0</b>   | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   |
| Alcohol Detection Systems DM-904             |           |           |           |           |            |            |            |            |            |            |            | 0          | 0          | 1          | 1          | 1          | 1          |
| <b>Schenectady</b>                           | <b>29</b> | <b>34</b> | <b>37</b> | <b>47</b> | <b>54</b>  | <b>59</b>  | <b>63</b>  | <b>69</b>  | <b>76</b>  | <b>84</b>  | <b>90</b>  | <b>103</b> | <b>108</b> | <b>112</b> | <b>123</b> | <b>122</b> | <b>130</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>3</b>  | <b>5</b>   | <b>6</b>   | <b>6</b>   | <b>9</b>   | <b>10</b>  | <b>11</b>  | <b>12</b>  | <b>10</b>  | <b>10</b>  | <b>10</b>  | <b>12</b>  | <b>12</b>  | <b>31</b>  |
| Smart Start 2020                             | 0         | 0         | 1         | 3         | 5          | 6          | 6          | 9          | 10         | 11         | 12         | 10         | 10         | 10         | 12         | 12         | 31         |
| Smart Start SS1-1000                         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>4</b>   | <b>7</b>   | <b>9</b>   | <b>9</b>   | <b>9</b>   | <b>12</b>  | <b>11</b>  | <b>10</b>  |
| Intoxalock 1001A                             | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| Intoxalock 1001A Advanced                    | 0         | 0         | 0         | 0         | 1          | 1          | 1          | 1          | 1          | 4          | 7          | 9          | 9          | 9          | 12         | 11         | 10         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Draeger XT                                   | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>23</b> | <b>27</b> | <b>28</b> | <b>35</b> | <b>39</b>  | <b>42</b>  | <b>46</b>  | <b>48</b>  | <b>55</b>  | <b>58</b>  | <b>58</b>  | <b>62</b>  | <b>63</b>  | <b>66</b>  | <b>69</b>  | <b>71</b>  | <b>70</b>  |
| Interceptor M-1                              | 23        | 27        | 28        | 35        | 39         | 42         | 46         | 48         | 55         | 58         | 58         | 62         | 63         | 66         | 69         | 71         | 70         |
| <b>National Interlock Service LTD</b>        | <b>6</b>  | <b>6</b>  | <b>6</b>  | <b>7</b>  | <b>7</b>   | <b>8</b>   | <b>8</b>   | <b>8</b>   | <b>8</b>   | <b>8</b>   | <b>10</b>  | <b>19</b>  | <b>23</b>  | <b>24</b>  | <b>27</b>  | <b>26</b>  | <b>19</b>  |
| LifeSafer FC100 camera                       | 0         | 0         | 0         | 1         | 1          | 2          | 2          | 2          | 2          | 8          | 10         | 19         | 23         | 24         | 25         | 24         | 17         |
| LifeSafer FC100 no camera                    | 6         | 6         | 6         | 6         | 6          | 6          | 6          | 6          | 6          | 0          | 0          | 0          | 0          | 0          | 2          | 2          | 2          |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>3</b>   | <b>2</b>   | <b>3</b>   | <b>3</b>   | <b>3</b>   | <b>3</b>   | <b>3</b>   | <b>3</b>   | <b>2</b>   | <b>0</b>   |
| Best Labs FR9000                             |           | 1         | 2         | 2         | 2          | 2          | 2          | 3          | 2          | 3          | 3          | 3          | 3          | 3          | 3          | 2          | 0          |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |           |           |           |            |            |            |            |            |            |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Alcohol Detection Systems DM-904             |           |           |           |           |            |            |            |            |            |            |            | 0          | 0          | 0          | 0          | 0          | 0          |

|  |          |          |          |           |           |           |           |           |           |           |           |           |           |           |           |           |           |
|--|----------|----------|----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| <b>Schoharie</b>                             | <b>1</b> | <b>2</b> | <b>3</b> | <b>4</b>  | <b>6</b>  | <b>6</b>  | <b>7</b>  | <b>7</b>  | <b>7</b>  | <b>9</b>  | <b>11</b> | <b>12</b> | <b>12</b> | <b>12</b> | <b>12</b> | <b>14</b> | <b>27</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>1</b> | <b>2</b> | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>11</b> |
| Smart Start 2020                             | 0        | 1        | 2        | 2         | 2         | 2         | 2         | 2         | 2         | 2         | 2         | 1         | 1         | 0         | 0         | 0         | 11        |
| Smart Start SS1-1000                         | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>2</b>  | <b>2</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>5</b>  | <b>6</b>  | <b>7</b>  | <b>7</b>  | <b>8</b>  | <b>8</b>  | <b>10</b> | <b>11</b> |
| Intoxalock 1001A                             | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         |
| Intoxalock 1001A Advanced                    | 0        | 0        | 0        | 0         | 2         | 2         | 3         | 3         | 3         | 4         | 5         | 6         | 6         | 7         | 7         | 9         | 10        |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  |
| Draeger XT                                   | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 1         | 1         | 1         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  |
| Interceptor M-1                              | 1        | 1        | 1        | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 2         |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 1         | 1         |
| LifeSafer FC100 no camera                    | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b> | <b>0</b> | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  |
| Best Labs FR9000                             |          | 0        | 0        | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |          |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |          |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Schuyler</b>                              | <b>8</b> | <b>7</b> | <b>8</b> | <b>11</b> | <b>14</b> | <b>14</b> | <b>14</b> | <b>17</b> | <b>16</b> | <b>16</b> | <b>14</b> | <b>15</b> | <b>16</b> | <b>15</b> | <b>13</b> | <b>14</b> | <b>10</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>0</b> | <b>1</b> | <b>4</b>  | <b>8</b>  | <b>9</b>  | <b>9</b>  | <b>11</b> | <b>10</b> | <b>9</b>  | <b>6</b>  | <b>6</b>  | <b>7</b>  | <b>6</b>  | <b>5</b>  | <b>5</b>  | <b>0</b>  |
| Smart Start 2020                             | 0        | 0        | 1        | 4         | 8         | 9         | 9         | 11        | 10        | 9         | 6         | 6         | 7         | 6         | 5         | 5         | 0         |
| Smart Start SS1-1000                         | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>3</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>3</b>  | <b>4</b>  | <b>5</b>  |
| Intoxalock 1001A                             | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 0         | 0         | 0         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 1         | 2         | 2         | 2         | 3         | 4         | 4         | 3         | 4         | 5         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>8</b> | <b>7</b> | <b>7</b> | <b>7</b>  | <b>6</b>  | <b>5</b>  | <b>5</b>  | <b>5</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  |
| Interceptor M-1                              | 8        | 7        | 7        | 7         | 6         | 5         | 5         | 5         | 4         | 4         | 4         | 4         | 4         | 4         | 4         | 4         | 4         |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| LifeSafer FC100 no camera                    | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |          |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |          |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |



|  |          |          |          |          |           |           |           |           |           |           |           |           |           |           |           |           |           |
|--|----------|----------|----------|----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| <b>Seneca</b>                                | <b>0</b> | <b>0</b> | <b>5</b> | <b>7</b> | <b>10</b> | <b>12</b> | <b>16</b> | <b>22</b> | <b>21</b> | <b>22</b> | <b>23</b> | <b>22</b> | <b>18</b> | <b>14</b> | <b>17</b> | <b>17</b> | <b>22</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>0</b> | <b>4</b> | <b>6</b> | <b>8</b>  | <b>10</b> | <b>14</b> | <b>20</b> | <b>17</b> | <b>17</b> | <b>15</b> | <b>14</b> | <b>9</b>  | <b>4</b>  | <b>4</b>  | <b>4</b>  | <b>6</b>  |
| Smart Start 2020                             | 0        | 0        | 4        | 6        | 8         | 10        | 14        | 20        | 17        | 17        | 15        | 14        | 9         | 4         | 4         | 4         | 6         |
| Smart Start SS1-1000                         | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>4</b>  | <b>4</b>  | <b>6</b>  | <b>7</b>  | <b>6</b>  | <b>9</b>  |
| Intoxalock 1001A                             | 0        | 0        | 0        | 0        | 1         | 1         | 1         | 1         | 3         | 3         | 3         | 4         | 4         | 5         | 6         | 5         | 8         |
| Intoxalock 1001A Advanced                    | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Interceptor M-1                              | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>0</b> | <b>1</b> | <b>1</b> | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>5</b>  | <b>4</b>  | <b>5</b>  | <b>4</b>  | <b>6</b>  | <b>7</b>  | <b>7</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         |
| LifeSafer FC100 no camera                    | 0        | 0        | 1        | 1        | 1         | 1         | 1         | 1         | 1         | 2         | 5         | 4         | 5         | 4         | 6         | 6         | 6         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |          |          |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |          |          |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>St. Lawrence</b>                          | <b>1</b> | <b>1</b> | <b>3</b> | <b>6</b> | <b>9</b>  | <b>11</b> | <b>14</b> | <b>18</b> | <b>19</b> | <b>22</b> | <b>22</b> | <b>23</b> | <b>20</b> | <b>17</b> | <b>15</b> | <b>15</b> | <b>16</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>0</b> | <b>1</b> | <b>1</b> | <b>2</b>  | <b>3</b>  | <b>6</b>  | <b>7</b>  | <b>8</b>  | <b>9</b>  | <b>10</b> | <b>10</b> | <b>7</b>  | <b>6</b>  | <b>6</b>  | <b>6</b>  | <b>2</b>  |
| Smart Start 2020                             | 0        | 0        | 1        | 1        | 2         | 3         | 6         | 7         | 8         | 9         | 10        | 10        | 7         | 6         | 6         | 6         | 2         |
| Smart Start SS1-1000                         | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>0</b> | <b>1</b> | <b>4</b> | <b>5</b>  | <b>6</b>  | <b>7</b>  | <b>10</b> | <b>10</b> | <b>11</b> | <b>10</b> | <b>11</b> | <b>11</b> | <b>9</b>  | <b>8</b>  | <b>8</b>  | <b>9</b>  |
| Intoxalock 1001A                             | 0        | 0        | 1        | 4        | 5         | 6         | 6         | 9         | 9         | 9         | 8         | 8         | 8         | 8         | 8         | 7         | 8         |
| Intoxalock 1001A Advanced                    | 0        | 0        | 0        | 0        | 0         | 0         | 1         | 1         | 1         | 2         | 2         | 3         | 3         | 1         | 0         | 1         | 1         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b> | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>2</b>  |
| Interceptor M-1                              | 1        | 1        | 1        | 1        | 1         | 1         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 2         |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b> | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         |
| LifeSafer FC100 no camera                    | 0        | 0        | 0        | 0        | 1         | 1         | 1         | 0         | 0         | 1         | 1         | 1         | 1         | 2         | 1         | 1         | 1         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0        | 0        | 0        | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 1         | 1         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |          |          |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  |
| Alcohol Detection Systems DM-904             |          |          |          |          |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 1         |

|  |            |            |            |            |            |            |            |            |            |            |            |            |            |            |            |            |            |
|--|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|
| <b>Steuben</b>                               | <b>3</b>   | <b>4</b>   | <b>4</b>   | <b>6</b>   | <b>7</b>   | <b>11</b>  | <b>18</b>  | <b>19</b>  | <b>26</b>  | <b>30</b>  | <b>35</b>  | <b>38</b>  | <b>43</b>  | <b>37</b>  | <b>37</b>  | <b>37</b>  | <b>41</b>  |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>2</b>   | <b>5</b>   | <b>5</b>   | <b>4</b>   | <b>4</b>   | <b>5</b>   |
| Smart Start 2020                             | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 1          | 1          | 1          | 1          | 2          | 5          | 5          | 4          | 4          | 5          |
| Smart Start SS1-1000                         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>3</b>   | <b>3</b>   | <b>7</b>   | <b>10</b>  | <b>12</b>  | <b>19</b>  | <b>23</b>  | <b>27</b>  | <b>31</b>  | <b>32</b>  | <b>28</b>  | <b>28</b>  | <b>28</b>  | <b>30</b>  |
| Intoxalock 1001A                             | 0          | 1          | 1          | 3          | 3          | 7          | 10         | 12         | 19         | 23         | 27         | 28         | 29         | 25         | 26         | 26         | 28         |
| Intoxalock 1001A Advanced                    | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 3          | 3          | 3          | 2          | 2          | 2          |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Draeger XT                                   | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>1</b>   | <b>1</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   |
| Interceptor M-1                              | 1          | 1          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 1          | 1          | 1          | 1          | 1          | 1          | 1          |
| <b>National Interlock Service LTD</b>        | <b>2</b>   | <b>2</b>   | <b>3</b>   | <b>3</b>   | <b>4</b>   | <b>4</b>   | <b>8</b>   | <b>6</b>   | <b>6</b>   | <b>6</b>   | <b>6</b>   | <b>4</b>   | <b>5</b>   | <b>3</b>   | <b>4</b>   | <b>4</b>   | <b>5</b>   |
| LifeSafer FC100 camera                       | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| LifeSafer FC100 no camera                    | 2          | 2          | 3          | 3          | 4          | 4          | 8          | 6          | 6          | 6          | 6          | 4          | 5          | 3          | 4          | 4          | 5          |
| <b>Sens_O-Lock of America, L.L.C.</b>        |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Best Labs FR9000                             |            | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Statewide Interlock Systemes, Inc.</b>    |            |            |            |            |            |            |            |            |            |            |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Alcohol Detection Systems DM-904             |            |            |            |            |            |            |            |            |            |            |            | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Suffolk</b>                               | <b>354</b> | <b>390</b> | <b>431</b> | <b>472</b> | <b>518</b> | <b>546</b> | <b>584</b> | <b>604</b> | <b>639</b> | <b>685</b> | <b>711</b> | <b>779</b> | <b>774</b> | <b>805</b> | <b>768</b> | <b>803</b> | <b>789</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>167</b> | <b>187</b> | <b>214</b> | <b>239</b> | <b>263</b> | <b>276</b> | <b>308</b> | <b>334</b> | <b>324</b> | <b>319</b> | <b>298</b> | <b>290</b> | <b>270</b> | <b>247</b> | <b>228</b> | <b>221</b> | <b>190</b> |
| Smart Start 2020                             | 48         | 73         | 102        | 136        | 167        | 184        | 223        | 257        | 255        | 254        | 243        | 239        | 225        | 205        | 190        | 190        | 166        |
| Smart Start SS1-1000                         | 119        | 114        | 112        | 103        | 96         | 92         | 85         | 77         | 69         | 65         | 55         | 51         | 45         | 42         | 38         | 31         | 24         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>   | <b>6</b>   | <b>14</b>  | <b>26</b>  | <b>40</b>  | <b>55</b>  | <b>66</b>  | <b>72</b>  | <b>93</b>  | <b>115</b> | <b>134</b> | <b>186</b> | <b>200</b> | <b>215</b> | <b>196</b> | <b>252</b> | <b>257</b> |
| Intoxalock 1001A                             | 0          | 3          | 8          | 14         | 21         | 28         | 31         | 33         | 40         | 40         | 37         | 39         | 42         | 40         | 11         | 9          | 6          |
| Intoxalock 1001A Advanced                    | 0          | 3          | 6          | 12         | 19         | 27         | 35         | 39         | 53         | 75         | 97         | 147        | 158        | 175        | 185        | 243        | 251        |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>52</b>  | <b>52</b>  | <b>54</b>  | <b>59</b>  | <b>59</b>  | <b>59</b>  | <b>53</b>  | <b>45</b>  | <b>49</b>  | <b>45</b>  | <b>37</b>  | <b>40</b>  | <b>38</b>  | <b>43</b>  | <b>39</b>  | <b>33</b>  | <b>27</b>  |
| Draeger XT                                   | 52         | 52         | 54         | 59         | 59         | 59         | 53         | 45         | 49         | 45         | 37         | 40         | 38         | 43         | 39         | 33         | 27         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>53</b>  | <b>60</b>  | <b>64</b>  | <b>66</b>  | <b>68</b>  | <b>72</b>  | <b>75</b>  | <b>80</b>  | <b>90</b>  | <b>98</b>  | <b>118</b> | <b>125</b> | <b>132</b> | <b>144</b> | <b>151</b> | <b>158</b> | <b>172</b> |
| Interceptor M-1                              | 53         | 60         | 64         | 66         | 68         | 72         | 75         | 80         | 90         | 98         | 118        | 125        | 132        | 144        | 151        | 158        | 172        |
| <b>National Interlock Service LTD</b>        | <b>82</b>  | <b>84</b>  | <b>84</b>  | <b>81</b>  | <b>87</b>  | <b>83</b>  | <b>81</b>  | <b>73</b>  | <b>82</b>  | <b>107</b> | <b>123</b> | <b>137</b> | <b>133</b> | <b>155</b> | <b>153</b> | <b>138</b> | <b>142</b> |
| LifeSafer FC100 camera                       | 0          | 0          | 3          | 4          | 11         | 13         | 16         | 16         | 30         | 56         | 76         | 92         | 94         | 116        | 122        | 109        | 122        |
| LifeSafer FC100 no camera                    | 82         | 84         | 81         | 77         | 76         | 70         | 65         | 57         | 52         | 51         | 47         | 45         | 39         | 39         | 31         | 29         | 20         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |            | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   |
| Best Labs FR9000                             |            | 1          | 1          | 1          | 1          | 1          | 1          | 0          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          |
| <b>Statewide Interlock Systemes, Inc.</b>    |            |            |            |            |            |            |            |            |            |            |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Alcohol Detection Systems DM-904             |            |            |            |            |            |            |            |            |            |            |            | 0          | 0          | 0          | 0          | 0          | 0          |

|  |          |           |           |           |           |           |           |           |           |           |           |           |           |           |           |           |           |
|--|----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| <b>Sullivan</b>                              | <b>1</b> | <b>5</b>  | <b>6</b>  | <b>12</b> | <b>19</b> | <b>26</b> | <b>28</b> | <b>29</b> | <b>31</b> | <b>46</b> | <b>39</b> | <b>39</b> | <b>40</b> | <b>37</b> | <b>40</b> | <b>50</b> | <b>49</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>1</b> | <b>2</b>  | <b>2</b>  | <b>3</b>  | <b>5</b>  | <b>6</b>  | <b>6</b>  | <b>6</b>  | <b>5</b>  | <b>4</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>4</b>  | <b>4</b>  | <b>8</b>  |
| Smart Start 2020                             | 1        | 2         | 2         | 3         | 5         | 6         | 6         | 6         | 5         | 4         | 3         | 3         | 3         | 3         | 4         | 4         | 8         |
| Smart Start SS1-1000                         | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>3</b>  | <b>4</b>  | <b>8</b>  | <b>10</b> | <b>14</b> | <b>16</b> | <b>17</b> | <b>20</b> | <b>20</b> | <b>16</b> | <b>16</b> | <b>18</b> | <b>16</b> | <b>19</b> | <b>26</b> | <b>26</b> |
| Intoxalock 1001A                             | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0        | 3         | 4         | 8         | 10        | 14        | 16        | 17        | 20        | 20        | 16        | 16        | 18        | 16        | 19        | 26        | 26        |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  |
| Interceptor M-1                              | 0        | 0         | 0         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 0         |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>3</b>  | <b>5</b>  | <b>5</b>  | <b>5</b>  | <b>5</b>  | <b>21</b> | <b>19</b> | <b>19</b> | <b>17</b> | <b>16</b> | <b>15</b> | <b>18</b> | <b>14</b> |
| LifeSafer FC100 camera                       | 0        | 0         | 0         | 0         | 2         | 3         | 5         | 5         | 5         | 19        | 18        | 17        | 16        | 15        | 15        | 18        | 14        |
| LifeSafer FC100 no camera                    | 0        | 0         | 0         | 0         | 1         | 2         | 0         | 0         | 0         | 2         | 1         | 2         | 1         | 1         | 0         | 0         | 0         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |           |           |           |           |           |           |           |           |           |           | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  |
| Alcohol Detection Systems DM-904             |          |           |           |           |           |           |           |           |           |           |           | 0         | 1         | 1         | 1         | 1         | 1         |
| <b>Tioga</b>                                 | <b>8</b> | <b>12</b> | <b>14</b> | <b>18</b> | <b>20</b> | <b>22</b> | <b>26</b> | <b>31</b> | <b>28</b> | <b>26</b> | <b>26</b> | <b>32</b> | <b>37</b> | <b>37</b> | <b>37</b> | <b>39</b> | <b>38</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>2</b>  | <b>4</b>  | <b>6</b>  | <b>7</b>  | <b>8</b>  | <b>8</b>  | <b>9</b>  | <b>8</b>  | <b>8</b>  | <b>6</b>  | <b>6</b>  | <b>7</b>  | <b>8</b>  | <b>9</b>  | <b>9</b>  | <b>9</b>  |
| Smart Start 2020                             | 0        | 2         | 4         | 6         | 7         | 8         | 8         | 9         | 8         | 8         | 6         | 6         | 7         | 8         | 9         | 9         | 9         |
| Smart Start SS1-1000                         | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>2</b>  | <b>2</b>  | <b>3</b>  | <b>4</b>  | <b>5</b>  | <b>7</b>  | <b>10</b> | <b>11</b> | <b>10</b> | <b>11</b> | <b>16</b> | <b>18</b> | <b>17</b> | <b>18</b> | <b>19</b> | <b>19</b> |
| Intoxalock 1001A                             | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0        | 2         | 2         | 3         | 4         | 5         | 7         | 10        | 11        | 10        | 11        | 16        | 18        | 17        | 18        | 19        | 19        |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  |
| Draeger XT                                   | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>5</b> | <b>5</b>  | <b>5</b>  | <b>6</b>  | <b>7</b>  | <b>7</b>  | <b>7</b>  | <b>8</b>  | <b>8</b>  | <b>8</b>  | <b>9</b>  | <b>10</b> | <b>11</b> | <b>10</b> | <b>9</b>  | <b>9</b>  | <b>7</b>  |
| Interceptor M-1                              | 5        | 5         | 5         | 6         | 7         | 7         | 7         | 8         | 8         | 8         | 9         | 10        | 11        | 10        | 9         | 9         | 7         |
| <b>National Interlock Service LTD</b>        | <b>3</b> | <b>3</b>  | <b>3</b>  | <b>3</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>2</b>  | <b>2</b>  |
| LifeSafer FC100 camera                       | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 0         | 2         | 2         |
| LifeSafer FC100 no camera                    | 3        | 3         | 3         | 3         | 2         | 2         | 2         | 2         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>2</b>  | <b>2</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0         | 0         | 0         | 0         | 0         | 2         | 2         | 1         | 0         | 0         | 0         | 0         | 1         | 1         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |           |           |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |           |           |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |

|  |           |           |           |           |           |           |           |           |           |           |           |           |            |            |            |            |            |
|--|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|------------|------------|------------|------------|------------|
| <b>Tompkins</b>                              | <b>26</b> | <b>28</b> | <b>27</b> | <b>38</b> | <b>42</b> | <b>50</b> | <b>54</b> | <b>49</b> | <b>51</b> | <b>57</b> | <b>61</b> | <b>57</b> | <b>52</b>  | <b>57</b>  | <b>58</b>  | <b>62</b>  | <b>60</b>  |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>  | <b>2</b>  | <b>2</b>  | <b>7</b>  | <b>9</b>  | <b>15</b> | <b>21</b> | <b>21</b> | <b>23</b> | <b>27</b> | <b>30</b> | <b>27</b> | <b>23</b>  | <b>27</b>  | <b>28</b>  | <b>28</b>  | <b>26</b>  |
| Smart Start 2020                             | 0         | 2         | 2         | 7         | 9         | 15        | 21        | 21        | 23        | 27        | 30        | 27        | 23         | 27         | 28         | 28         | 26         |
| Smart Start SS1-1000                         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>2</b>  | <b>5</b>  | <b>6</b>  | <b>8</b>  | <b>8</b>  | <b>8</b>  | <b>8</b>  | <b>9</b>  | <b>11</b> | <b>15</b> | <b>15</b>  | <b>16</b>  | <b>16</b>  | <b>17</b>  | <b>18</b>  |
| Intoxalock 1001A                             | 0         | 0         | 2         | 5         | 6         | 8         | 8         | 8         | 8         | 8         | 11        | 12        | 12         | 13         | 13         | 13         | 14         |
| Intoxalock 1001A Advanced                    | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 0         | 3         | 3          | 3          | 3          | 4          | 4          |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Draeger XT                                   | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Interceptor M-1                              | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          |
| <b>National Interlock Service LTD</b>        | <b>26</b> | <b>26</b> | <b>23</b> | <b>26</b> | <b>25</b> | <b>25</b> | <b>23</b> | <b>18</b> | <b>18</b> | <b>19</b> | <b>19</b> | <b>14</b> | <b>13</b>  | <b>13</b>  | <b>13</b>  | <b>16</b>  | <b>15</b>  |
| LifeSafer FC100 camera                       | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 2         | 3         | 2         | 2          | 2          | 2          | 4          | 3          |
| LifeSafer FC100 no camera                    | 26        | 26        | 23        | 26        | 25        | 25        | 23        | 18        | 18        | 17        | 16        | 12        | 11         | 11         | 11         | 12         | 12         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   |
| Best Labs FR9000                             |           | 0         | 0         | 0         | 2         | 2         | 2         | 2         | 2         | 2         | 1         | 1         | 1          | 1          | 1          | 1          | 1          |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |           |           |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Alcohol Detection Systems DM-904             |           |           |           |           |           |           |           |           |           |           |           | 0         | 0          | 0          | 0          | 0          | 0          |
| <b>Ulster</b>                                | <b>3</b>  | <b>5</b>  | <b>12</b> | <b>15</b> | <b>24</b> | <b>33</b> | <b>42</b> | <b>46</b> | <b>43</b> | <b>78</b> | <b>85</b> | <b>98</b> | <b>103</b> | <b>103</b> | <b>101</b> | <b>106</b> | <b>105</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>3</b>  | <b>5</b>  | <b>6</b>  | <b>9</b>  | <b>11</b> | <b>12</b> | <b>14</b> | <b>15</b> | <b>18</b>  | <b>16</b>  | <b>17</b>  | <b>17</b>  | <b>22</b>  |
| Smart Start 2020                             | 0         | 0         | 0         | 0         | 2         | 4         | 5         | 8         | 10        | 11        | 14        | 15        | 18         | 16         | 17         | 17         | 22         |
| Smart Start SS1-1000                         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 0         | 0         | 0          | 0          | 0          | 0          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>4</b>  | <b>6</b>  | <b>7</b>  | <b>9</b>  | <b>8</b>  | <b>8</b>  | <b>11</b> | <b>17</b> | <b>17</b>  | <b>14</b>  | <b>17</b>  | <b>18</b>  | <b>17</b>  |
| Intoxalock 1001A                             | 0         | 0         | 1         | 1         | 3         | 5         | 6         | 8         | 7         | 7         | 10        | 17        | 17         | 14         | 17         | 18         | 17         |
| Intoxalock 1001A Advanced                    | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 1         | 1         | 1         | 0         | 0          | 0          | 0          | 0          | 0          |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Draeger XT                                   | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0          | 0          | 0          | 0          | 0          |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   |
| Interceptor M-1                              | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 1          | 1          | 1          | 1          | 1          |
| <b>National Interlock Service LTD</b>        | <b>2</b>  | <b>3</b>  | <b>8</b>  | <b>11</b> | <b>16</b> | <b>21</b> | <b>27</b> | <b>26</b> | <b>20</b> | <b>55</b> | <b>57</b> | <b>63</b> | <b>65</b>  | <b>69</b>  | <b>64</b>  | <b>68</b>  | <b>62</b>  |
| LifeSafer FC100 camera                       | 0         | 1         | 1         | 2         | 2         | 4         | 5         | 5         | 4         | 4         | 3         | 5         | 5          | 7          | 5          | 6          | 8          |
| LifeSafer FC100 no camera                    | 2         | 2         | 7         | 9         | 14        | 17        | 22        | 21        | 16        | 51        | 54        | 58        | 60         | 62         | 59         | 62         | 54         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |           | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>3</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>   | <b>3</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   |
| Best Labs FR9000                             |           | 1         | 2         | 2         | 1         | 1         | 2         | 2         | 3         | 2         | 2         | 2         | 2          | 3          | 2          | 2          | 2          |
| <b>Statewide Interlock Systemes, Inc.</b>    |           |           |           |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>1</b>   |
| Alcohol Detection Systems DM-904             |           |           |           |           |           |           |           |           |           |           |           | 0         | 0          | 0          | 0          | 0          | 1          |

|  |          |          |          |           |           |           |           |           |           |           |           |           |           |           |           |           |           |
|--|----------|----------|----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| <b>Warren</b>                                | <b>6</b> | <b>7</b> | <b>9</b> | <b>13</b> | <b>14</b> | <b>16</b> | <b>18</b> | <b>20</b> | <b>24</b> | <b>24</b> | <b>27</b> | <b>36</b> | <b>37</b> | <b>37</b> | <b>37</b> | <b>39</b> | <b>40</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>1</b> | <b>1</b> | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>3</b>  | <b>6</b>  | <b>7</b>  | <b>7</b>  | <b>7</b>  | <b>7</b>  | <b>6</b>  |
| Smart Start 2020                             | 0        | 1        | 1        | 1         | 1         | 1         | 1         | 2         | 2         | 2         | 3         | 6         | 7         | 7         | 7         | 7         | 6         |
| Smart Start SS1-1000                         | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>0</b> | <b>1</b> | <b>2</b>  | <b>2</b>  | <b>2</b>  | <b>3</b>  | <b>5</b>  | <b>8</b>  | <b>8</b>  | <b>9</b>  | <b>10</b> | <b>10</b> | <b>10</b> | <b>10</b> | <b>12</b> | <b>14</b> |
| Intoxalock 1001A                             | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 0         | 0         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0        | 0        | 1        | 2         | 2         | 2         | 3         | 5         | 8         | 7         | 8         | 9         | 9         | 10        | 10        | 12        | 14        |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>6</b> | <b>6</b> | <b>7</b> | <b>9</b>  | <b>10</b> | <b>12</b> | <b>12</b> | <b>12</b> | <b>13</b> | <b>12</b> | <b>13</b> | <b>14</b> | <b>14</b> | <b>13</b> | <b>13</b> | <b>13</b> | <b>16</b> |
| Interceptor M-1                              | 6        | 6        | 7        | 9         | 10        | 12        | 12        | 12        | 13        | 12        | 13        | 14        | 14        | 13        | 13        | 13        | 16        |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>0</b> | <b>0</b> | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  | <b>6</b>  | <b>6</b>  | <b>7</b>  | <b>7</b>  | <b>7</b>  | <b>4</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0        | 1         | 1         | 1         | 2         | 1         | 1         | 2         | 2         | 6         | 6         | 7         | 7         | 7         | 4         |
| LifeSafer FC100 no camera                    | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |          |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |          |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Washington</b>                            | <b>6</b> | <b>7</b> | <b>7</b> | <b>9</b>  | <b>12</b> | <b>12</b> | <b>12</b> | <b>14</b> | <b>14</b> | <b>15</b> | <b>10</b> | <b>16</b> | <b>16</b> | <b>17</b> | <b>19</b> | <b>21</b> | <b>24</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  |
| Smart Start 2020                             | 0        | 0        | 0        | 0         | 1         | 1         | 1         | 1         | 1         | 0         | 0         | 1         | 1         | 1         | 1         | 1         | 2         |
| Smart Start SS1-1000                         | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  | <b>2</b>  |
| Intoxalock 1001A                             | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| Intoxalock 1001A Advanced                    | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 1         | 1         | 2         | 2         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Draeger XT                                   | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>6</b> | <b>6</b> | <b>6</b> | <b>8</b>  | <b>10</b> | <b>10</b> | <b>11</b> | <b>13</b> | <b>13</b> | <b>13</b> | <b>7</b>  | <b>10</b> | <b>12</b> | <b>14</b> | <b>16</b> | <b>17</b> | <b>18</b> |
| Interceptor M-1                              | 6        | 6        | 6        | 8         | 10        | 10        | 11        | 13        | 13        | 13        | 7         | 10        | 12        | 14        | 16        | 17        | 18        |
| <b>National Interlock Service LTD</b>        | <b>0</b> | <b>0</b> | <b>0</b> | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>2</b>  | <b>3</b>  | <b>4</b>  | <b>2</b>  | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>2</b>  |
| LifeSafer FC100 camera                       | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 1         | 2         | 2         | 1         | 1         | 1         | 2         |
| LifeSafer FC100 no camera                    | 0        | 0        | 0        | 0         | 0         | 0         | 0         | 0         | 0         | 1         | 2         | 2         | 0         | 0         | 0         | 0         | 0         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |          | <b>1</b> | <b>1</b> | <b>1</b>  | <b>1</b>  | <b>1</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Best Labs FR9000                             |          | 1        | 1        | 1         | 1         | 1         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         | 0         |
| <b>Statewide Interlock Systemes, Inc.</b>    |          |          |          |           |           |           |           |           |           |           |           | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  | <b>0</b>  |
| Alcohol Detection Systems DM-904             |          |          |          |           |           |           |           |           |           |           |           | 0         | 0         | 0         | 0         | 0         | 0         |

|  |            |            |            |            |            |            |            |            |            |            |            |            |            |            |            |            |            |
|--|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|
| <b>Wayne</b>                                 | <b>3</b>   | <b>7</b>   | <b>11</b>  | <b>17</b>  | <b>20</b>  | <b>25</b>  | <b>33</b>  | <b>41</b>  | <b>45</b>  | <b>52</b>  | <b>57</b>  | <b>63</b>  | <b>66</b>  | <b>69</b>  | <b>62</b>  | <b>58</b>  | <b>61</b>  |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>   | <b>1</b>   | <b>3</b>   | <b>7</b>   | <b>9</b>   | <b>11</b>  | <b>14</b>  | <b>19</b>  | <b>23</b>  | <b>26</b>  | <b>25</b>  | <b>29</b>  | <b>29</b>  | <b>28</b>  | <b>21</b>  | <b>21</b>  | <b>23</b>  |
| Smart Start 2020                             | 0          | 1          | 3          | 7          | 9          | 11         | 14         | 19         | 23         | 26         | 25         | 29         | 29         | 28         | 21         | 21         | 23         |
| Smart Start SS1-1000                         | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>   | <b>3</b>   | <b>5</b>   | <b>7</b>   | <b>8</b>   | <b>11</b>  | <b>16</b>  | <b>19</b>  | <b>19</b>  | <b>22</b>  | <b>27</b>  | <b>31</b>  | <b>32</b>  | <b>35</b>  | <b>35</b>  | <b>31</b>  | <b>32</b>  |
| Intoxalock 1001A                             | 0          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 2          | 2          | 2          | 1          | 1          | 1          |
| Intoxalock 1001A Advanced                    | 0          | 2          | 4          | 6          | 7          | 10         | 15         | 18         | 18         | 21         | 26         | 29         | 30         | 33         | 34         | 30         | 31         |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   |
| Draeger XT                                   | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 2          | 0          | 1          | 1          | 1          | 1          | 1          |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   |
| Interceptor M-1                              | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 1          | 2          | 2          | 2          | 2          | 2          | 2          | 2          |
| <b>National Interlock Service LTD</b>        | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   | <b>2</b>   |
| LifeSafer FC100 camera                       | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 1          | 1          | 1          | 2          | 2          | 2          | 2          | 2          |
| LifeSafer FC100 no camera                    | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Sens_O-Lock of America, L.L.C.</b>        |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>0</b>   |
| Best Labs FR9000                             |            | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Statewide Interlock Systemes, Inc.</b>    |            |            |            |            |            |            |            |            |            |            |            | <b>0</b>   | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   |
| Alcohol Detection Systems DM-904             |            |            |            |            |            |            |            |            |            |            |            | 0          | 0          | 1          | 1          | 1          | 1          |
| <b>Westchester</b>                           | <b>187</b> | <b>205</b> | <b>233</b> | <b>245</b> | <b>269</b> | <b>295</b> | <b>340</b> | <b>370</b> | <b>391</b> | <b>414</b> | <b>444</b> | <b>459</b> | <b>461</b> | <b>462</b> | <b>480</b> | <b>490</b> | <b>500</b> |
| <b>1A Smart Start, Inc.</b>                  | <b>5</b>   | <b>11</b>  | <b>21</b>  | <b>27</b>  | <b>36</b>  | <b>44</b>  | <b>61</b>  | <b>74</b>  | <b>82</b>  | <b>91</b>  | <b>101</b> | <b>109</b> | <b>109</b> | <b>98</b>  | <b>104</b> | <b>104</b> | <b>112</b> |
| Smart Start 2020                             | 4          | 9          | 19         | 25         | 34         | 42         | 60         | 73         | 82         | 91         | 101        | 109        | 109        | 98         | 104        | 104        | 112        |
| Smart Start SS1-1000                         | 1          | 2          | 2          | 2          | 2          | 2          | 1          | 1          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          | 0          |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>   | <b>1</b>   | <b>2</b>   | <b>5</b>   | <b>5</b>   | <b>6</b>   | <b>8</b>   | <b>9</b>   | <b>12</b>  | <b>12</b>  | <b>10</b>  | <b>13</b>  | <b>13</b>  | <b>13</b>  | <b>12</b>  | <b>20</b>  | <b>23</b>  |
| Intoxalock 1001A                             | 0          | 1          | 2          | 5          | 5          | 5          | 6          | 7          | 9          | 9          | 9          | 10         | 10         | 10         | 9          | 13         | 14         |
| Intoxalock 1001A Advanced                    | 0          | 0          | 0          | 0          | 0          | 1          | 2          | 2          | 3          | 3          | 1          | 3          | 3          | 3          | 3          | 7          | 9          |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>39</b>  | <b>43</b>  | <b>51</b>  | <b>50</b>  | <b>53</b>  | <b>57</b>  | <b>67</b>  | <b>84</b>  | <b>77</b>  | <b>81</b>  | <b>86</b>  | <b>87</b>  | <b>86</b>  | <b>88</b>  | <b>96</b>  | <b>99</b>  | <b>102</b> |
| Draeger XT                                   | 39         | 43         | 51         | 50         | 53         | 57         | 67         | 84         | 77         | 81         | 86         | 87         | 86         | 88         | 96         | 99         | 102        |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>47</b>  | <b>53</b>  | <b>55</b>  | <b>62</b>  | <b>65</b>  | <b>68</b>  | <b>70</b>  | <b>72</b>  | <b>76</b>  | <b>77</b>  | <b>80</b>  | <b>80</b>  | <b>81</b>  | <b>81</b>  | <b>83</b>  | <b>80</b>  | <b>77</b>  |
| Interceptor M-1                              | 47         | 53         | 55         | 62         | 65         | 68         | 70         | 72         | 76         | 77         | 80         | 80         | 81         | 81         | 83         | 80         | 77         |
| <b>National Interlock Service LTD</b>        | <b>96</b>  | <b>97</b>  | <b>104</b> | <b>101</b> | <b>109</b> | <b>120</b> | <b>133</b> | <b>130</b> | <b>140</b> | <b>149</b> | <b>156</b> | <b>162</b> | <b>164</b> | <b>170</b> | <b>172</b> | <b>176</b> | <b>173</b> |
| LifeSafer FC100 camera                       | 14         | 15         | 24         | 25         | 35         | 36         | 45         | 48         | 48         | 56         | 62         | 66         | 69         | 74         | 73         | 74         | 75         |
| LifeSafer FC100 no camera                    | 82         | 82         | 80         | 76         | 74         | 84         | 88         | 82         | 92         | 93         | 94         | 96         | 95         | 96         | 99         | 102        | 98         |
| <b>Sens_O-Lock of America, L.L.C.</b>        |            | <b>0</b>   | <b>0</b>   | <b>0</b>   | <b>1</b>   | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>4</b>   | <b>4</b>   | <b>11</b>  | <b>8</b>   | <b>8</b>   | <b>11</b>  | <b>12</b>  | <b>10</b>  | <b>12</b>  |
| Best Labs FR9000                             |            | 0          | 0          | 0          | 1          | 0          | 1          | 1          | 4          | 4          | 11         | 8          | 8          | 11         | 12         | 10         | 12         |
| <b>Statewide Interlock Systemes, Inc.</b>    |            |            |            |            |            |            |            |            |            |            |            | <b>0</b>   | <b>0</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   | <b>1</b>   |
| Alcohol Detection Systems DM-904             |            |            |            |            |            |            |            |            |            |            |            | 0          | 0          | 1          | 1          | 1          | 1          |

| Wyoming                                      | 2           | 3           | 4           | 6           | 8           | 10          | 11          | 13          | 14          | 15          | 16          | 15          | 16          | 17          | 18          | 17          | 18          |
|--|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>1</b>    | <b>2</b>    | <b>2</b>    | <b>3</b>    | <b>4</b>    | <b>4</b>    | <b>4</b>    | <b>3</b>    | <b>4</b>    | <b>5</b>    | <b>5</b>    | <b>5</b>    | <b>6</b>    |
| Smart Start 2020                             | 0           | 0           | 0           | 0           | 1           | 2           | 2           | 3           | 4           | 4           | 4           | 3           | 4           | 5           | 5           | 5           | 6           |
| Smart Start SS1-1000                         | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>1</b>    | <b>1</b>    | <b>2</b>    | <b>2</b>    | <b>2</b>    | <b>2</b>    | <b>3</b>    | <b>4</b>    | <b>4</b>    | <b>4</b>    | <b>4</b>    | <b>4</b>    | <b>3</b>    | <b>3</b>    |
| Intoxalock 1001A                             | 0           | 0           | 0           | 1           | 1           | 1           | 1           | 1           | 1           | 1           | 0           | 0           | 0           | 0           | 0           | 0           | 0           |
| Intoxalock 1001A Advanced                    | 0           | 0           | 0           | 0           | 0           | 1           | 1           | 1           | 1           | 2           | 4           | 4           | 4           | 4           | 4           | 3           | 3           |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    |
| Draeger XT                                   | 0           | 0           | 0           | 0           | 0           | 0           | 1           | 1           | 1           | 1           | 1           | 1           | 1           | 1           | 1           | 1           | 1           |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>2</b>    | <b>3</b>    | <b>4</b>    | <b>5</b>    | <b>6</b>    | <b>6</b>    | <b>6</b>    | <b>7</b>    | <b>7</b>    | <b>7</b>    | <b>7</b>    | <b>7</b>    | <b>7</b>    | <b>7</b>    | <b>8</b>    | <b>8</b>    | <b>8</b>    |
| Interceptor M-1                              | 2           | 3           | 4           | 5           | 6           | 6           | 6           | 7           | 7           | 7           | 7           | 7           | 7           | 7           | 8           | 8           | 8           |
| <b>National Interlock Service LTD</b>        | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    |
| LifeSafer FC100 camera                       | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           |
| LifeSafer FC100 no camera                    | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           |
| <b>Sens_O-Lock of America, L.L.C.</b>        |             | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    |
| Best Labs FR9000                             |             | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           |
| <b>Statewide Interlock Systemes, Inc.</b>    |             |             |             |             |             |             |             |             |             |             |             | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    |
| Alcohol Detection Systems DM-904             |             |             |             |             |             |             |             |             |             |             |             | 0           | 0           | 0           | 0           | 0           | 0           |
| <b>Yates</b>                                 | <b>1</b>    | <b>9</b>    | <b>11</b>   | <b>12</b>   | <b>13</b>   | <b>14</b>   | <b>16</b>   | <b>12</b>   | <b>12</b>   | <b>10</b>   | <b>10</b>   | <b>11</b>   | <b>12</b>   | <b>15</b>   | <b>18</b>   | <b>17</b>   | <b>20</b>   |
| <b>1A Smart Start, Inc.</b>                  | <b>0</b>    | <b>1</b>    | <b>2</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>3</b>    | <b>3</b>    | <b>2</b>    | <b>3</b>    | <b>1</b>    | <b>3</b>    | <b>4</b>    | <b>6</b>    | <b>8</b>    | <b>8</b>    | <b>12</b>   |
| Smart Start 2020                             | 0           | 1           | 2           | 1           | 1           | 1           | 3           | 3           | 2           | 3           | 1           | 3           | 4           | 6           | 8           | 8           | 12          |
| Smart Start SS1-1000                         | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           |
| <b>Consumer Safety Technology, Inc.</b>      | <b>0</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>2</b>    | <b>3</b>    | <b>3</b>    | <b>4</b>    | <b>4</b>    | <b>6</b>    | <b>6</b>    | <b>6</b>    | <b>6</b>    | <b>7</b>    | <b>6</b>    | <b>5</b>    |
| Intoxalock 1001A                             | 0           | 1           | 1           | 1           | 1           | 2           | 3           | 3           | 4           | 4           | 5           | 4           | 4           | 3           | 3           | 1           | 1           |
| Intoxalock 1001A Advanced                    | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 1           | 2           | 2           | 3           | 4           | 5           | 4           |
| <b>Draeger Safety Diagnostics, Inc.</b>      | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>1</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    |
| Draeger XT                                   | 1           | 1           | 1           | 1           | 1           | 1           | 1           | 1           | 1           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           |
| <b>Interceptor Ignition Interlocks, Inc.</b> | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    |
| Interceptor M-1                              | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           |
| <b>National Interlock Service LTD</b>        | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>2</b>    | <b>2</b>    | <b>3</b>    | <b>3</b>    | <b>3</b>    | <b>3</b>    |
| LifeSafer FC100 camera                       | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 1           | 1           | 2           | 2           | 2           | 2           |
| LifeSafer FC100 no camera                    | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 0           | 1           | 1           | 1           | 1           | 1           | 1           |
| <b>Sens_O-Lock of America, L.L.C.</b>        |             | <b>6</b>    | <b>7</b>    | <b>9</b>    | <b>10</b>   | <b>10</b>   | <b>9</b>    | <b>5</b>    | <b>5</b>    | <b>3</b>    | <b>3</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    |
| Best Labs FR9000                             |             | 6           | 7           | 9           | 10          | 10          | 9           | 5           | 5           | 3           | 3           | 0           | 0           | 0           | 0           | 0           | 0           |
| <b>Statewide Interlock Systemes, Inc.</b>    |             |             |             |             |             |             |             |             |             |             |             | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    | <b>0</b>    |
| Alcohol Detection Systems DM-904             |             |             |             |             |             |             |             |             |             |             |             | 0           | 0           | 0           | 0           | 0           | 0           |
| <b>Grand Total</b>                           | <b>2132</b> | <b>2374</b> | <b>2723</b> | <b>3137</b> | <b>3612</b> | <b>4017</b> | <b>4514</b> | <b>4843</b> | <b>5227</b> | <b>5708</b> | <b>5987</b> | <b>6306</b> | <b>6428</b> | <b>6561</b> | <b>6601</b> | <b>6777</b> | <b>6680</b> |